



(a) $\Delta f_{\text{detune}} = 0$


$|r|^2 = 0.000$

(b) $\Delta f_{\text{detune}} = +0.5\Delta\nu_{\text{FWHM}}$


$|r|^2 = 0.500$

(c) $\Delta f_{\text{detune}} = -0.5\Delta\nu_{\text{FWHM}}$


$|r|^2 = 0.500$

(d) $\Delta f_{\text{detune}} = +1.5\Delta\nu_{\text{FWHM}}$

$|r|^2 = 0.900$

(e) $\Delta f_{\text{detune}} = -1.5\Delta\nu_{\text{FWHM}}$

$|r|^2 = 0.900$

(f) $\Delta f_{\text{detune}} = \text{FSR}/2 (180^\circ)$

$|r|^2 = 1.000$

