

Motorhome Habitation Service Record

Habsheet
195-197 Wood Street
E17 3NU
London, Uk
07506 078673
Habsheet.com

CUSTOMER	MAKE AND MODEL	VIN	MILEAGE
Harry Little (Sample)	Swift Boloro 675	2GS36GS 244253	65245

Underbody	P	F	N/A	R	Comments
Corner steadies		F			Failed on inspection. Attention needed.
Folding step		F			Failed on inspection. Attention needed.
Underslung tanks and pipework	P				

Electrical	P	F	N/A	R	Comments
Fridge on 230V and 12V	P				
Leisure battery	P				
Interior lighting and equipment	P				
Fuse box and ratings	P				
Awning light	P				
ELV wiring – visual inspection	P				
Mains inlet and hook-up lead				R	Rectified at the service
Earth bond continuity	P				
Consumer unit – RCD load test	P				
230V sockets	P				
Electric awning	P				
230V appliances, fans and lighting – operation	P				
Aftermarket equipment	P				
Charge voltage	P				

Gas	P	F	N/A	R	Comments
Regulator, hose, pipework and manifold	P				
Tightness test	P				
LPG tank security	P				
Cylinder security			N/A		
Dispersal vents clear	P				
Gas appliances – operation and flame failure devices	P				

Water	P	F	N/A	R	Comments
Pump, pressure switch and microswitches	P				
Taps, valves, pipes and tank	P				
Water inlets	P				
Waste system			N/A		
Toilet	P				

Bodywork	P	F	N/A	R	Comments
Doors and windows	P				
Bodywork and roof – general condition	P				
External seals and bonded joints	P				
Body attachments – ladders, racks, aerials, security	P				
Floor	P				
Furniture	P				
Blinds and fly screens	P				
Rising roof	P				
Damp test – recorded on the damp report	P				

Motorhome Habitation Service Record

Habsheet
195-197 Wood Street
E17 3NU
London, Uk
07506 078673
Habsheet.com

CUSTOMER

Harry Little (Sample)

MAKE AND MODEL

Swift Boloro 675

VIN

2GS36GS 244253

Ventilation

P F N/A R

Comments

Fixed ventilation, low and high	P				
Roof lights	P				

Fire and safety

P F N/A R

Comments

Smoke alarm – test button, circuit, sounder	P				
CO alarm – test button, circuit, sounder	P				
Fire extinguisher – housing security	P				

Smoke alarm expiry

09/2033

CO alarm expiry

N/A

Fire extinguisher expiry

N/A

Service information, additional work and observations

Repaired

[illegible]

EICR offered

Yes / No / **N/A**

- | | | | |
|---|--|--|--|
| ☒ Gas turned off | ☒ Cupboards closed and latched | ☒ Lights off | ☐ Old parts left with the vehicle |
| ☒ Roof lights latched | ☒ Exterior lockers locked | ☒ Water pump off | ☒ Protective coverings removed |
| ☒ Windows locked | ☒ Exterior door locked | ☒ 12V master off | ☒ Service book stamped |

Battery rest voltage (V)	12.9 V
--------------------------	--------

RCD trip time at $1 \times I_{\Delta n}$ (ms)	26/36
---	-------

Earth bond, chassis (Ω)	0.3
----------------------------------	-----

Earth bond, gas (Ω)	0.04
------------------------------	------

Charger voltage (V) 13.2 V

Gas hose expiry/ manufacture date	11/2022
-----------------------------------	---------

Regulator age	2015
---------------	------

Note Appliances are checked for operation only, not against the manufacturer's performance figures. Further servicing may be needed for warranty purposes.

This record describes the motorhome at the time the service was completed. It is not evidence of its condition at any other time.

A habitation service does not cover the base vehicle or its road-legal requirements.

Service technician		Signature	
Customer signature		Date	20/09/2026

Motorhome Damp Report


Habsheet
195-197 Wood Street
E17 3NU
London, Uk
07506 078673
Habsheet.com

CUSTOMER
Harry Little (Sample)


MAKE AND MODEL
Swift Boloro 675

VIN
2GS36GS 244253


REGISTRATION
M44 DDG




FRONT



NEARSIDE




REAR




OFFSIDE

Calibration check figure
14
Weather conditions
Dry
Ambient temperature
18°C
Meter — make and model
Protimeter survey master



CEILING



FLOOR

Service technician		Signature	
Customer signature		Date	20/09/2026