Michael Commission and Commission of the Commiss						Ιμ,	lla
LDI Ro, 0x4	8-01	00 1000)				
C=0 Z=0	N=0	V=0	S=0	H=0	T=o	I=0	
LSL -> R.	= 1001	0000		1⊕V	·		
·				<u>^</u>		· · · · · · · · · · · · · · · · · · ·	
C=0 Z=0				S=0	H=1	T=0	I=0
		NBC					
BST Roo4							
=0 Z=0	N=1	V=1	S=() H	=1	T=1	.I=
					1		
ADD ROODX	80						<u> </u>
C = 1 - Z = 0	N=0	V=1	S=L	H=C) T=	1	_ =0
SFI					3.		
4. 2. 1. 4. 1. kg							
C=1 Z=0	N=0	V-1	5=1	H=0	T = 1	I =	1
		# <i>U</i>		•		1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	
1001 0	000				1		
+ 1000 0	000						11.
1 = 0001 0	000						14
	V-VV						