
Electrical Tasks



```
set position v to 0

count up v by 1 for position v from 1 to 179 do

rotate servo on pin 9 v to position degrees

wait 20 milliseconds v

count up v by 1 for i v from 179 to 1 do

rotate servo on pin 9 v to position degrees
```