

MAINTENANCE & INSPECTION REPORT

Pump Unit 7 — Industrial Process Area

Asset ID	PU-07
Equipment	Centrifugal Process Pump
Area	Process Bay B — Line 3
Operating Status	Operational
Report Period	March–June 2026

1. Inspection Record — 14 March 2026

Pump Unit 7 was inspected on 14 March 2026 during the scheduled maintenance window. The bearing temperature was recorded as nominal at 42°C. Lubricant level was normal. The air filter was replaced during the visit. No abnormal vibration was recorded in the inspection notes.

Technician on record: R. Kulkarni **Inspection status:** Passed

2. Maintenance Measurements

Parameter	14 Mar 2026	Acceptance / Note
Bearing temperature	42°C	Nominal
Lubricant level	Normal	Within operating range
Air filter	Replaced	Replacement completed
Vibration	No abnormal reading	No corrective action required
Pump status	Operational	Returned to service

3. Follow-up Service Schedule

The next scheduled service for Pump Unit 7 was set for 12 June 2026. The service plan called for verification of bearing condition, lubricant level, filter condition, vibration status, and general pump operation.

Date	Activity	Responsible Technician	Result / Status
14 Mar 2026	Routine inspection	R. Kulkarni	Passed
14 Mar 2026	Air filter replacement	R. Kulkarni	Completed
12 Jun 2026	Scheduled service	Maintenance Team	Planned

4. Safety and Operating Notes

- Maintenance personnel must isolate the pump before opening guards or performing mechanical work.
- The pump should not be returned to service until the work area is clear and the maintenance checklist is signed.
- Bearing temperature should be recorded during routine inspections because a change from the recorded nominal condition may indicate a developing issue.
- Replacement parts should be recorded against the Pump Unit 7 asset ID for traceability.

5. Asset History Notes

Record	Detail
Asset	PU-07 / Pump Unit 7
Last inspection	14 March 2026
Bearing temperature at inspection	42°C — nominal
Lubricant	Normal
Filter	Air filter replaced
Technician	R. Kulkarni
Next scheduled service	12 June 2026

6. Troubleshooting Reference

The following internal reference notes are included to make the document suitable for retrieval and reasoning tests. They are not a record of faults on 14 March 2026.

Observed condition	Recommended first check	Escalation
Bearing temperature rises above normal	Check lubricant level and airflow	Inspect bearing if condition persists
Abnormal vibration	Check mounting and alignment	Mechanical inspection
Reduced flow	Check filter and suction path	Inspect pump and process line
Unusual noise	Check for loose components or cavitation indicators	Stop and inspect if severe

TEST QUESTION

Using the maintenance record and follow-up schedule, identify the Pump Unit 7 inspection date, calculate the exact number of days until the next scheduled service, state the bearing temperature and lubricant condition recorded at inspection, identify the maintenance action performed, and explain which troubleshooting check would become the first priority if the bearing temperature later increased above its recorded nominal condition.