

INCIDENT REPORT - WORKSHOP FLOOR

Date: 02 August 2026, 14:20 hrs.

A minor chemical spill occurred near Tank 3 during a scheduled transfer operation. Approximately 2 liters of solvent leaked from a loose coupling. The area was cordoned off within 5 minutes and no injuries were reported.

The spill kit was deployed per protocol SOP-118 and the area was cleared for re-entry after ventilation checks passed.

Investigation has been assigned to the EHS team, with a full report due within 5 working days.