

DP1000 Report

Project Information

Customer: Casco Operator: 101399
WorkNo: RWO0187448 LotNum: 0
IC Manufacture: Microchip IC Module: PIC16F15325-I/SL[SOIC14]
File Checksum: 00003854 Option Checksum: 8598
Chip Checksum: 369A
 Yield: 99.00 %
UPH: 1674 Expect Input: 100
Input: 100 Expect Output: 100
Output: 99 NG Input: 0
NG: 1 LeadScan NG: 0
Markscan2 NG: 0 Last Stop Time: 6/5/2025 11:29:33 AM
Start Time: 6/5/2025 11:22:50 AM Work Time: 00:03:35 Idle Time: 00:02:58
Alert Time: 00:02:08

Others Information

Inspection Flow

Markscan2: #Error

Leadscan: No

Socket Information

DP1000 Report

Programmer		OK	NG	Total
	Socket	Count	Count	Count
Programmer 1	Socket1	13	0	13
	Socket2	13	0	13
	Socket3	13	0	13
	Socket4	13	0	13
	Socket5	0	0	0
	Socket6	0	0	0
	Socket7	0	0	0
	Socket8	0	0	0
	Socket9	0	0	0
	Socket10	0	0	0
	Socket11	0	0	0
	Socket12	0	0	0
Programmer 2		OK	NG	Total
	Socket1	12	0	12
	Socket2	12	0	12
	Socket3	11	1	12
	Socket4	12	0	12
	Socket5	0	0	0
	Socket6	0	0	0
	Socket7	0	0	0
	Socket8	0	0	0
	Socket9	0	0	0
	Socket10	0	0	0
	Socket11	0	0	0
	Socket12	0	0	0

Inspection Information

Key	AOIErr	LeadScan
0	0	0
1	0	0

SerialNo Information

First Serial Number:

External Serialization Program:

Last Serial Number:

Environment

WindowsOS: Microsoft Windows NT 6.2.9200.0

DP1000 Version: 1.3.18.143

Dediware Version: 3.1.2.1

DWServer Version: 3.20.5.13

DP1000 Report

Firmware Version: