## Midwest Scientific Instruments

## Bulletin Board Updates

P.N. 978, SI-1, Serial Interface

REVISE value of R21 and R22 FROM: 100 ohm, W TO: 100 ohm, W

P.N. 979, CP-1, CPU


- 1. REVISE value of R14 FROM: 120 ohm, W TO: 100 ohm, W
- 2. REVISE C10 FROM: DISC, .1UF TO: TANT, 1UF INSTALL C10 with positive side directly above R9 and negative side directly above PIN 8 of IC18 as shown:

C 10 Pin 8

3. ADD C19, ELEC, 25UF, 25V R9
INSTALL C19 at the 50 Pin Connector with positive side at PIN 21, +8VUR, and negative side at PIN 26,GND.

4. Add R19, 100 ohm ±5%, 4W

INSTALL R19 from C11 to Y1 as shown:



R19 Y1 C110

COMPONENT SIDE VIEW

REVISE value of R3 FROM: 68K ohm TO: 22K ohm

P.N. 986, RAM-16, 16K RAM

ADD C58, ELEC, 25UF, 25V


P.N. 985, AC-1, Audio Cassette Interface

INSTALL C58 at the 50 Pin Connector with positive side at PIN 21, +8VUR, and negative side at PIN 26, GND.

ALL BOARDS WITH 7805, 7812 &/OR 7905 VOLTAGE REGULATORS (except EPR-8)

REVISE the bypass capacitor on the output

FROM: DISC, .01UF OR DISC, .1UF TO: TANT, 1UF
INSTALL as shown:



HD-8/R, 10 Megabyte Disk Drive -- Strap Configuration

- 1. REMOVE rear panel to expose the wire-wrap jumper options.
- 2. REMOVE the jumper between PINS 51 & 52.
- INSTALL jumper between PINS 50 & 52 (enables the head retract on controller power loss feature).
- 4. REMOVE the jumper between PINS 16 & 17.
- 5. INSTALL jumper between PINS 16 & 18 (enables the head restore on disk read error feature).