Без экрана				Сталь 2			Сталь 5		Сталь 10		
f, Гц	V_0	U_0	V_e	U_e	$ \eta_m $	V_e	U_e	$ \eta_m $	V_e	U_e	$ \eta_m $
20	1 000	16.70	52.00	16.00	18	20.000	15.60	47	18.000	15.10	50
50	1 000	5.59	68.00	4.50	12	9.000	4.20	83	1.500	4.00	477
100	1 000	4.40	54.00	3.20	13	7.500	2.79	85	0.350	1.60	1039
200	1 000	1.90	40.00	1.05	14	2.200	0.97	232	0.040	0.83	10921
500	1 000	1.14	22.00	0.68	27	0.250	0.60	2105	0.010	0.58	50877
1000	1 000	0.73	9.00	0.52	79	0.035	0.50	19568	0.005	0.48	131506
2000	1 000	0.65	3.20	0.54	260	0.030	0.48	24614	_	_	_
5000	1 000	0.58	0.18	0.54	5172	_	_	_	_	_	_
10000	700	0.31	0.07	0.38	12258	_	_	_	-	_	_