Без экрана			Латунь 2			Латунь 5			Латунь 10		
f, Гц	V_0	U_0	V_e	U_e	$ \eta_m $	V_e	U_e	$ \eta_m $	V_e	U_e	$ \eta_m $
20	1 000	16.70	930	16.30	1.05	910.0	16.30	1.07	870.00	16.30	1.12
50	1000	5.59	870	5.59	1.15	820.0	5.59	1.22	620.00	5.19	1.50
100	1000	4.40	770	4.40	1.30	650.0	4.40	1.54	490.00	4.40	2.04
200	1000	1.90	680	2.09	1.62	540.0	2.24	2.18	380.00	2.40	3.32
500	1000	1.14	500	1.30	2.28	300.0	1.46	4.27	180.00	1.60	7.80
1000	1000	0.73	390	0.92	3.23	170.0	1.00	8.06	90.00	1.27	19.33
2000	1000	0.65	240	0.92	5.90	80.0	1.00	19.23	34.00	1.30	58.82
5000	1000	0.58	100	0.78	13.45	28.0	0.88	54.18	3.80	1.28	580.73
10000	700	0.31	39	0.32	18.53	5.2	0.33	143.30	0.45	0.62	3111.07