# Chapter 1. Characterization of solid particles


- 1.1 Properties of single particles: size, shape
- 1.2 Particle size distribution: mean diameter
- 1.3 Methods to measure particle size: sieving, elutriation

J.M. Coulson and J.F. Richardson pp 1 - 17



#### Physichochemical properties of solid particles

## Single particles



Size, Shape, hardness, compressive resistance, electrical coli charge, (intraparticle) porosity, ...

Cement particles

#### Bulk solids



Particle size distribution, (interparticle) porosity, humidity, agglomeration, flowability, ...

## Solids suspensions

Heterogeneous mixture of a fluid (gas or liquid) with a solid



Particle size distribution, Concentration of solids, viscosity of suspension, flocculation, settleability, ...



## Properties of single particles: shape

#### Regular shape.

Regular shapes have well-defined geometry by a mathematical equation, thus their volume, surface area, etc... may be calculated by well defined mathematical formulas. For example, a sphere:

## Sphere



$$\frac{\pi d^3}{6} = \frac{4\pi r^3}{3}$$

Surface area:  $~\pi d^2 = 4\pi r^2$ 

Projected area in a plane:  $\frac{\pi d^2}{4} = \pi r^2$ 

- A sphere is a special regular shape because it is the only shape that is completely symmetrical irrespective of orientation.
- A cube or a cylinder are also regular shapes but their symmetry depends on orientation

### Properties of single particles: shape

#### Complex regular shapes

- Complex regular shapes are many times used in packed columns in chemical and biological engineering (distillation columns, absorption columns, chromatographic columns, packed bed reactors, etc..)
- They are typically designed to maximize surface area per unit volume!!!!
- They enable improved packing properties, e.g. regular packing with more particles per unit volume
- More expensive but with higher performance
- (More to this in chapter 5. Flow of fluids in packed columns)

## Raschig Rings







**Nutter Ring** 






## Properties of single particles: shape

<u>Irregular shape</u>: Cannot be defined by a mathematical equation. Undefined size that varies with orientation. Several possibilities to define a characteristic dimension, *d*:

- Diameter of sphere with same volume as particle (see below)
- Diameter of sphere with same surface as particle
- Diameter of sphere with same surface per unit volume as particle




Defining the characteristic dimension of particle, d, as the diameter of an hypothetical sphere with the same volume of particle

$$V_{particle} = V_{shpere} = \frac{\pi d^3}{6}$$
  $d = \frac{3}{3}$ 

$$d = \sqrt[3]{\frac{6V_{particle}}{\pi}}$$


## Properties of single particles: size

Examples of particles in Chemical and Biological Engineering and respective sizes (adapted from Fig 1.2 in Coulson and Richardon)





## Particle Size Distribution (PSD)



Bulk solids or solid suspensions typically comprehend particles of many different sizes

Particle size
distributions
provide detailed
information of
particle sizes and
respective quantities
in a given sample



#### Methods to measure PSD: sieving

- Sievers consist of a sequence of large-to-low mesh sizes to separate particles based on their size
- Mechanical vibration is applied to avoid agglomeration of particles
- Laboratory sievers are used as a certified Analytical technique to determine particle size distribution in the range  $> 50~\mu m$
- Industrial sievers are used to separate solids of different sizes in discontinuous or continuous mode



Industrial Siever






#### Methods to measure PSD: sieving

#### Standardized sequence of mesh sizes for certified PSD measurement

Table 1.1. Standard sieve sizes


British fine mesh (B.S.S. 410) <sup>(3)</sup>			I.M.M. <sup>(4)</sup>			U.S. Tyler <sup>(5)</sup>			U.S. A.S.T.M. <sup>(5)</sup>		
Sieve no.	Nominal aperture		Sieve	Nominal aperture		Sieve	Nominal aperture		Sieve	Nominal aperture	
	in.	μm	no.	in.	μm	no.	in.	μm	no.	in.	μm
						325	0.0017	43	325	0.0017	44
						270	0.0021	53	270	0.0021	53
300	0.0021	53				250	0.0024	61	230	0.0024	6
240	0.0026	66	200	0.0025	63	200	0.0029	74	200	0.0029	74
200	0.0030	76							170	0.0034	88
170	0.0035	89	150	0.0033	84	170	0.0035	89			
150	0.0041	104				150	0.0041	104	140	0.0041	104
120	0.0049	124	120	0.0042	107	115	0.0049	125	120	0.0049	12:
100	0.0060	152	100	0.0050	127	100	0.0058	147	100	0.0059	150
			90	0.0055	139	80	0.0069	175	80	0.0070	17
85	0.0070	178	80	0.0062	157	65	0.0082	208	70	0.0083	21
			70	0.0071	180				60	0.0098	25
72	0.0083	211	60	0.0083	211	60	0.0097	246	50	0.0117	29
60	0.0099	251							45	0.0138	35
52	0.0116	295	50	0.0100	254	48	0.0116	295	40	0.0165	42
			40	0.0125	347	42	0.0133	351	35	0.0197	50
44	0.0139	353				35	0.0164	417	30	0.0232	59
36	0.0166	422	30	0.0166	422	32	0.0195	495			
30	0.0197	500				28	0.0232	589			
25	0.0236	600									
22	0.0275	699	20	0.0250	635	24	0.0276	701	25	0.0280	710
18	0.0336	853	16	0.0312	792	20	0.0328	833	20	0.0331	84
16	0.0395	1003				16	0.0390	991	18	0.0394	100
14	0.0474	1204	12	0.0416	1056	14	0.0460	1168	16	0.0469	1190
12	0.0553	1405	10	0.0500	1270	12	0.0550	1397			
10	0.0660	1676	8	0.0620	1574	10	0.0650	1651	14	0.0555	1410
8	0.0810	2057				9	0.0780	1981	12	0.0661	168
7	0.0949	2411				8	0.0930	2362	10	0.0787	200
6	0.1107	2812	5	0.1000	2540	7	0.1100	2794	8	0.0937	238
5	0.1320	3353				6	0.1310	3327			
						5	0.1560	3962	7	0.1110	2839
						4	0.1850	4699			
									6	0.1320	3360
									5	0.1570	400
									4	0.1870	476






## **PSD: Frequency** *versus* Cumulative

Bulk solids or solids suspensions typically contain particles with many different sizes. **Particle size distributions** characterize the mixture in terms of quantity of particles (e.g. mass fraction, x) as function of respective size (e.g. diameter, d). There are two ways to represent particle size distribution: **A** – Frequency distribution, **B** – Cumulative distribution






{Any point in curve reads mass fraction, x, with size  $\leq d$ }




### **PSD:** examples

#### Examples: (1) Chinese Hamster Ovary (CHO) cells, (2) Portland cement










https://www.beckman.pt/resources/reading-material/application-notes/cellularanalysis-using-the-coulter-principle




The Influence of Ambient Temperature on High Performance Concrete Properties, DOI: •10.3390/ma13204646



#### **PSD:** distribution base

The distribution base refers to the method to define the quantity of solids. Quantity of solids is typically measured as number or mass. Number fraction, *n*, may be converted to mass, x, volume, v, surface, s, or length, l, fraction, based on particle size and geometric considerations. Suppose a solid sample is fractionated in fractions of equal sized particles by a siever:

fraction i of ni particles with size di



number fraction Length fraction

$$n_i$$
,  $l_i = \frac{n_i d_i}{\sum n_k d_k}$ 


Surface fraction

Volume fraction = Mass fraction

$$l_{i} = \frac{n_{i}d_{i}}{\sum n_{k}d_{k}} \qquad s_{i} = \frac{n_{i}d_{i}^{2}}{\sum n_{k}d_{k}^{2}} \qquad v_{i} = \frac{n_{i}d_{i}^{3}}{\sum n_{k}d_{k}^{3}} = x_{i} = \frac{n_{i}d_{i}^{3}}{\sum n_{k}d_{k}^{3}}$$

#### **PSD:** distribution base

In PSD curves, the distribution base (e.g. "quantity" of particles) may be defined in different ways. This results in different distribution curves for the same solids sample processed in a sieving experiment.






#### **PSD:** mean diameter

## Mean diameter based on weight, $\bar{d}_x$

$$\bar{d}_{x} = \frac{\int d \, dx}{\int dx}$$

$$\bar{d}_{x} = \frac{\sum d_{i} x_{i}}{\sum x_{i}}$$





#### **PSD:** mean diameter

 $\overline{d}_x$  - Mean diameter based on weight:

$$\bar{d}_x = \frac{\int d \, dx}{\int dx}$$

$$\bar{d}_x = \frac{\sum d_i x_i}{\sum x_i}$$

 $\overline{d}_n$  - Mean diameter based on number:

$$\bar{d}_n = \frac{\int d \ dn}{\int dn}$$

$$\bar{d}_n = \frac{\sum d_i n_i}{\sum n_i}$$

 $\overline{d}_V$  - Mean diameter based on volume:

$$\bar{d}_V = \frac{\int d \ dv}{\int dv}$$

$$\bar{d}_V = \frac{\sum d_i v_i}{\sum v_i}$$

 $\overline{d}_S$  - Mean diameter based on surface:

$$\bar{d}_S = \frac{\int d \, ds}{\int ds}$$

$$\bar{d}_S = \frac{\sum d_i s_i}{\sum s_i}$$

 $\overline{d}_L$  - Mean diameter based on length:

$$\bar{d}_L = \frac{\int d \ dl}{\int dl}$$

$$\bar{d}_L = \frac{\sum d_i l_i}{\sum l_i}$$



#### **PSD:** mean diameter

## Measurement in weight, x

Measurement in number, n

Mean diameter based on volume (or weight)

$$\bar{d}_{x} = \bar{d}_{v}$$

Mean diameter based on surface

$$ar{d}_{\mathcal{S}}$$

 $= \frac{\sum x_i}{\sum \frac{x_i}{d_i}}$ 

$$\frac{\sum n_i d_i^3}{\sum n_i d_i^2} \qquad \begin{array}{c} \text{Home}_i \\ \text{work!} \end{array}$$


Mean diameter based on length

$$ar{d}_L$$

$$= \frac{\sum \frac{x_i}{d_i}}{\sum \frac{x_i}{d_i^2}}$$


$$= \frac{\sum n_i d_i^2}{\sum n_i d_i}$$

#### Methods to measure particle size






#### Methods to measure particle size: elutriation



**Elutriation** is a particle classification and/or separation process based on the density and size of particles through the motion of a carrying fluid (gas or liquid). The smaller and less dense particles will be dragged out on the top of the column (**fine particles stream**). The bigger and more dense particles will settle in the bottom of the column (**coarse particles stream**).







#### **Exercises I.1-4**

#### I - CLASSIFICAÇÃO DE PARTÍCULAS SÓLIDAS

 A análise por peneiração duma amostra de um sólido finamente moido produziu o seguinte resultado:

Dimensão da (mm)	abertura	Percentagem do produto (% em mimero)			
Passando por	6.00	100			
Retido em	4.00	6			
Retido em	2.00	18			
Retido em	0.75	23			
Retido em	0.50	28			
Retido em	0.25	17			
Retido em	0.125	5			
Passando por	0.125	3			

#### Determine e represente graficamente:

- a) Curva de distribuição de frequência em número
- b) Curva de distribuição cumulativa em número
- c) Complemente os gráficos anteriores com as distribuições em comprimento, superficie, volume e peso.

#### Calcule o tamanho médio da amostra de sólido:

- d) Determine os diâmetros médios baseados em comprimento, superficie, volume e peso
- e) Determine o diâmetro do comprimento médio, superficie média, volume médio e peso médio
- A análise por peneiração duma amostra de um sólido finamente moido produziu o seguinte resultado:

Dimensão da (mm)	abertura	Percentagem do produto (% em peso)			
Passando por	12.00	100			
Retido em	8.00	35			
Retido em	4.00	32			
Retido em	2.00	17			
Retido em	1.00	8			
Passando por	1.00	8			

a) Determine os diâmetros médios baseados em comprimento, superficie, volume e peso

- b) Determine o diâmetro do comprimento médio, superficie média, volume médio e peso médio
- 3. A análise granulométrica de um material em pó numa base de peso é representada por uma linha recta que vai de 0% em peso na dimensão de partícula de 1 mícron até 100% em peso na dimensão de partícula de 101 mícrons.
  - a) Calcular o diâmetro médio em volume das partículas que constituem o sistema.
  - b) Calcular o diâmetro médio superficial das partículas que constituem o sistema.
- 4. As equações que dão a curva de distribuição de números para um material em pó são da/dd = d para a gama de tamanhos de 0-10 mícrons, e da/dd = 100 000/d⁴ para a gama de tamanhos de 10-100 mícrons. Esboçar as curvas de distribuição de número, superfície e peso. Calcular o diâmetro médio superfícial para o pó.

Explicar sucintamente o modo como se obteriam experimentalmente os dados para a construção destas curvas.

