Chapter 2. Size reduction of solids


- 2.1 Introductory concepts
- 2.2 Mechanisms of size reduction
- 2.3 Equipment for size reduction
- 2.4 Energy for size reduction
- 2.5 Exercises.

J.M. Coulson and J.F. Richardson pp 95 - 144




In chemical and biological engineering, it is often necessary either to decrease or to increase the particle size. For example, the starting material is too coarse, and possibly in the form of large rocks, and the final product needs to be a fine powder. The particle size will have to be progressively reduced in stages.

Feed: Large rocks





What is a size reduction unit operation? A size reduction unit operation (a crusher or a mill) spends energy (**E**) to reduce the size of solids from the average size L_1 to the final average size $L_2 \ll L_1$





Solid properties that highly impact the performance of a size reduction process and that influences the choice of the equipment:

- Size- depending on the size of the feed and product, reduction is classified as coarse, intermediate and fine reduction; the energy needed is very different
- Compressive strength- minimum compressive (slow) strength that causes solid fracture
- **Brittleness ("fragilidade"):** Brittle materials are characterized by little deformation, poor capacity to resist impact and vibration of load, high compressive strength, and low tensile strength. Most of inorganic non-metallic materials are brittle materials, e.g. glass
- Stickiness ("pegajosidade"): Stickiness is a property that causes considerable difficulty in reducing the size because the material gets to adhere to the equipment
- Soapiness (propriedade de sabão): a measure of the friction coefficient of the material surface
- Humidity: humidity content between 5-50% should be avoided as solids tend to cake, do not flow well; energy increases
- **Friability:** it is the tendency of the material to fracture during normal handling; a crystalline material will break along well defined planes; the energy to break the material will increase as the material gets smaller.



Compressive strength (resistência ao esmagamento) , f_c [N/m2] is the compressive force required to cause rupture of the particle

Rock	Tensile Strength (MPa)	Compressive Strength (MPa)
Limestone Sandstone Sandstone Sandstone Mudstone Limestone Limestone Ironstone Sandstone	18.00 ± 0.62 (20) 19.17 ± 0.21 (23) 23.10 ± 0.48 (19) 24.21 ± 0.83 (8) 35.17 ± 3.17 (4) 36.28 ± 1.24 (24) 38.76 ± 2.69 (23) 44.28 ± 4.48 (5) 65.66 ± 0.83 (11)	$41.45 \pm 3.52 (4)$ $77.59 \pm 1.59 (5)$ $80.83 \pm 2.21 (10)$ $90.48 \pm 3.86 (4)$ $50.07 \pm 3.79 (4)$ $142.55 \pm 6.14 (5)$ $142.97 \pm 19.10 (8)$ $190.69 \pm 17.93 (4)$ $167.66 \pm 9.86 (5)$


Table 2. Mean tensile strength and compressive strength for selected sedimentary rock types (after Johnson and Degraff, 1988).



Mechanisms of size reduction

Four main types of forces develop simultaneously in any size reduction equipment. Different machines will however develop a predominant type of force.


1- Impact






particle concussion by a single rigid force

2 - Compression




particle disintegration by two rigid forces

3 - Shear



produced by a fluid or by particle—particle interaction


4 - Attrition



arising from particles scraping against one another or against a rigid surface




Mechanisms of size reduction



- The compressive strength, f_c [N/m2], of a solid material tends to increase as the size of the solid decreases
- As consequence, the energy per unit mass [J/Kg] spent to reduce the size of a given material is higher in the small size range

Mechanisms of size reduction

Effect of progressive gridding on the solid size distribution. The size distribution dynamically changes with mill revolutions



- Persistent mode
 (stable final size) is
 determined by the
 internal structure of the
 material
- The relative quantities
 persistent and
 transitory modes is
 determined by the size
 reduction machine
 (predominant type of
 force and power)


(taken from Coulson & Richardson)



Very low energy utilization efficiency between 0.1 - 2.0%

- In producing inelastic deformation which results in effective size reduction L1→L2 and creation of new surface.
- In producing elastic deformation of the particles before fracture occurs
- In causing elastic distortion of the equipment.
- In friction between particles, and between particles and the machine.
- In noise, heat and vibration in the plant, and
- In friction losses in the plant itself.





Depending on the size of the feed and of the desired product, reduction equipment is classified as: (1)Fine, (2)Intermediate, (3)Coarse; different laws of energy are applied in each case

	FINE	INTERMEDIATE	COARSE
Feed size (L1)	5-2 mm	50-5 mm	1500-40 mm
Product size (L2)	<0,1 mm (powder)	5-0,1 (granular/powder)	50-5 mm (large/granular)
Examples of equipment	Ball mill Buhrstone mill Roller mill NEI pendulum mill Griffin mill Ring roller mill Tube mill	Crushing rolls Disc crusher Edge runner mill Hammer mill Single roll crusher Pin mill Symons disc crusher	Blake jaw crusher Stag jaw crusher Dodge jaw crusher Gyratory crusher



Empirical law of energy for size reduction:

$$\frac{dE}{dL} = -C L^p$$

E – energy spent for size reduction [kJ/kg]

L - size of solids [m]

C – empirical constant related to the solid properties and equipment properties

p - empirical constant related to the size of solids

$$p=-1$$
: coarse reduction, $p=-3/2$: intermediate reduction, $p=-2$: fine reduction



Rittinger's law (p=-2)

$$E = C \left(\frac{1}{L_2} - \frac{1}{L_1} \right)$$

Bond's law
$$(p = -3/2)$$

$$E = C\left(\frac{1}{L_2} - \frac{1}{L_1}\right)$$
 $E = 2C\left(\frac{1}{\sqrt{L_2}} - \frac{1}{\sqrt{L_1}}\right)$

Kick's law
$$(p = -1)$$

$$E = C \ln \left(\frac{L_1}{L_2} \right)$$

$$E = K_R f_c \left(\frac{1}{L_2} - \frac{1}{L_1} \right)$$

$$E = K_R f_c \left(\frac{1}{L_2} - \frac{1}{L_1} \right)$$
 $E = E_i \sqrt{\left(\frac{100}{L_2} \right)} \left(1 - \frac{1}{\sqrt{q}} \right)$

$$E = K_K f_c \ln \left(\frac{L_1}{L_2} \right)$$

Fine reduction

- Energy is utilized more efficiently
- Energy increases as the feed size decreases

Intermediate reduction

- Intermediate efficiency
- Energy increases as the feed size decreases

Coarse reduction

- Energy is utilized less efficiently
- Energy increases with the ratio of feed/product sizes



Rittinger's law

Bond's law

Kick's law

$$E = K_R f_c \left(\frac{1}{L_2} - \frac{1}{L_1} \right)$$

$$E = K_R f_c \left(\frac{1}{L_2} - \frac{1}{L_1} \right) \qquad E = E_i \sqrt{\left(\frac{100}{L_2} \right)} \left(1 - \frac{1}{\sqrt{q}} \right) \quad E = K_K f_c \ln \left(\frac{L_1}{L_2} \right)$$

Fine reduction

Intermediate reduction

Coarse reduction

E – energy spent for size reduction, [KJ/kg]

 K_R , K_K Rittinger, Kick constant respectively; empririal constant related to the equipment; without physical meaning

 f_{c} —Compressive strength [MPa]; caracterizes the solid material that is being reduced

For bond's law only:

E_i - the work index: amount of energy required to reduce unit mass of material from L1=∞ to a size L2=100 µm

$$q = L_1/L_2$$




Determination of average size (L1, L2)

- L1 or L2 are calculated as the mean diameter based on volume (d_V see chapter 1) from the feed and product size distributions
- Alternatively, **Bond's diameter** (d_{Bond}) provides a good estimate. **Bond's diameter** (d_{Bond}) is defined as the mesh size through which 80% of material passes, in a sieving characterization experiment



Ball mill (Moinho de bolas)





- Hollow rotating cylindrical chamber
- Griding balls inside [0,3-0,4 v/v]
- The balls are typically made of steel
- Prevalent forces:Impact/Attrition
- Classified as <u>fine size</u>
 <u>reduction</u>



Ball mill (Moinho de bolas)

• A **ball mill** has a critical rotation speed $(w_c, rad/s)$ that must be avoided. At the critical point, the ball (with mass m and radius r) is subject to a centrifugal force (mu^2/r) equal to the gravitational force (mg)



$$m\frac{u^2}{r} = mg \qquad m\,rw_c^2 = mg \Leftrightarrow$$

$$w_c = \sqrt{\frac{g}{r}}$$


• The optimal rotation speed $(w_o, rad/s)$ should be chosen below the critical value $(w_c, rad/s)$ in order to maximize milling efficiency:


$$w_o \sim [1/2, 2/3] \times w_c$$

 W_c - [rad/s, r] – mill internal radius [m], g = 9,81 [m/s²]



Crushing rolls (triturador de rolos)






- Two parallel rollers (compact cylinders) rotating in opposite direction (inwards)
- In its simple version, only one of the rollers is mechanically driven
- The distance between the rollers may be adjusted to the feed size and desired product size
- Main forces: compressive/attrition
- Classified as <u>intermediate size</u> <u>reduction</u>




Crushing rolls (triturador de rolos)



$$\cos\left(\frac{\beta}{2}\right) = \frac{r_1 + b/2}{r_1 + r_2}$$

- Roll radius, r_1
- The distance between the rolls, \boldsymbol{b} , must be adjusted to the feed particle size, \boldsymbol{r}_2
- Nip angle, β, should be at most 31° degrees

Jaw crusher (Triturador de maxilas)





- Two jaws with compatible toothed surface
- Fixed jaw + swing jaw
- Angle of nip ~30° degree
- Main force applied: compressive
- Classified as <u>coarse</u>
 <u>reduction</u>



Exercises II.1–7

II - REDUÇÃO DA GRANULOMETRIA DE SÓLIDOS

- Tritura-se um material mun triturador de maxilas Blake e reduz-se o tamanho médio das particulas de 50 mm para 10 mm, com um consumo de energia de 13.0 kw s kg³. Qual será o consumo de energia necessário para triturar o mesmo material do tamanho médio 75 mm até à dimenção média de 25 mm.
 - (a) supondo aplicável a lei de Rittinger, e
 - (b) supondo aplicável a lei de Kick?

Qual destes resultados considera de maior confiança e porquê?

2. Usou-se um triturador para triturar um material cuja resistência à compressão era de 22.5 MN/m². O tamanho da alimentação era menor que 50 mm, maior que 40 mm e a potência necessária era 13.0 kw s kg¹. A análise por peneiração do produto produziu o seguinte resultado:

Dimensão da (mm)	abertura	Percentagem do produto (% em mimero)
Passando por	6.00	100
Retido em	4.00	26
Retido em	2.00	18
Retido em	0.75	23
Retido em	0.50	8
Retido em	0.25	17
Retido em	0.125	3
Passando por	0.125	5

Qual seria a potência necessária para triturar um kg por segundo de um material com resistência à compressão de 45 MN/m² a partir de uma alimentação de menor que 45 mm, maior que 40 mm para dar um produto de tamanho médio de 0.50 mm?

3. Um triturador para moer cal de 70 MN/m² de resistência à compressão desde o tamanho médio de 6 mm de diâmetro até ao tamanho médio de 0.1 mm de diâmetro, precisa de ter 9 kw. A mesma máquina usa-se para triturar domolite ao mesmo ritmo de produção desde o tamanho médio de 6 mm de diâmetro até um produto que contém 20% com um diâmetro médio de 0.25 mm, 60% com um diâmetro médio de 0.25 mm, tendo o restante um diâmetro médio 0.085 mm. Fazer a estimativa da potência em kw necessária para accionar o

triturador, supondo que a resistência ao esmagamento da domolite é 100 MN/m² e que a trituração obedece à lei de Rittinger.

4. Se se regularem uns rolos de moagem de 1 m de diâmetro de tal modo que as superficies de moagem fiquem à distância de 12.5 mm e o ângulo de presa for 31°, qual é o tamanho máximo de particulas que se deveria introduzir nos rolos?

Se a capacidade real da máquina é 12% da teórica, calcular o ritmo de produção em kg por segundo, quando a funcionar a 2.0 Hz, se a superficie de trabalho dos rolos tiver 0.4 m de comprimento e se a alimentação pesar 2500 kg/m².

Um triturador mói sal desde um tamanho médio de partícula de 45 mm até um produto

Dimensão (mm)	% do produto em número
12.5	0.5
7.5	7.5
5.0	45.0
2.5	19.0
1.5	16.0
0.75	8.0
0.40	3.0
0.20	1.0

e ao fazer isto consome 21 kJ/kg de material triturado.

Calcular a potência necessária para triturar o mesmo material ao mesmo caudal, a partir de uma alimentação com um tamanho médio de 25 mm até um produto com com um tamanho médio de 1 mm.

- 6. Um moinho de bolas com 1.2 m de diâmetro está a trabalhar a 0.80 Hz verificando-se que o moinho não está a trabalhar satisfatoriamente. Sugere alguma modificação nas condições de funcionamento?
- 7. É preciso fornecer 3 kw a uma máquina para esta triturar material ao caudal de 0.3 kg/s desde cubos de 12.5 mm até um produto com os seguintes tamanhos (% em número):

80%	3.175 mm
10%	2.5 mm
10%	2.25 mm

Que potência em kw teria de fornecer-se a esta máquina para triturar 0.3 kg/s do mesmo material de cubos de 7.5 mm até cubos de 2.0 mm?

4

5

