

TECHIN 514 A


PCB Design
Yunxiao DU

Sensor


Electronic component list

#	Reference	Qty	Value	Footprint	DNP
1	J1	1	Battery	Connector_PinSocket_1.00mm:PinSocket_1x02_P1.00mm_Vertical	
2	J2, J3, J4	3	Conn_01x02_Socket	Connector_PinSocket_1.00mm:PinSocket_1x02_P1.00mm_Vertical	
3	R1, R2, R3	3	10k	Resistor_SMD:R_0805_2012Metric_Pad1.20x1.40mm_HandSolder	
4	U1	1	~	footprints:XIAO_ESP32	
5	U3	1	ADS1115IDGS	Package_SO:TSSOP-10_3x3mm_P0.5mm	

Circuit in the Schematic Editor window of KiCad



Circuit board in the PCB Editor window of KiCad




Display

Electronic component list

#	Reference	Qty	Value	Footprint	DNP
1	D1, D2, D3	3	1655	footprints:LED_1655	
2	J1	1	Conn_01x02_Pin	Connector_PinHeader_1.00mm:PinHeader_1x02_P1.00mm_Vertical	
3	J5	1	Battery	Connector_PinSocket_1.00mm:PinSocket_1x02_P1.00mm_Vertical	
4	M1	1	Stepper_Motor_bipolar	footprints:x27_stepper	
5	U2	1	~	footprints:XIAO_ESP32	

Circuit in the Schematic Editor window of KiCad



Circuit board in the PCB Editor window of KiCad

