Motor temperature calibration: rider checklist

Your steps only, from the full plan (docs/motor_temperature_calibration_plan.pdf). Claude sends every command. Where it says **tell Claude**, nothing is sent until you confirm in chat.

Every measurement gives a small jerk of the rear wheel. When a step says wheel up: rear wheel off the ground (or rear brake held firmly), and keep hands and feet clear of the wheel.

1. At home, the day before

phase 1 · about 5 min

- ☐ Scooter on its stand, rear wheel off the ground (or hold the rear brake firmly). Keep clear of the wheel.
- ☐ **Tell Claude** you are ready. Claude runs five quick measurements (five small jerks).

2. Next morning, before riding

phase 2 · about 5 min

- ☐ Scooter parked indoors for at least 4 hours (overnight is best).
- ☐ Switch it on. Read the room temperature on a household thermometer: _____ °C
- ☐ Rear wheel up (or brake held). **Tell Claude** the room temperature and confirm. Claude stores the cold reference.
- ☐ Laptop helper window open, scooter on Wi-Fi.

3. Before leaving

optional

- ☐ For shell readings: bring the IR thermometer and stick a piece of matt tape on the rear hub shell.

4. First 10 minutes of the ride

phase 3

- ☐ Ride normally.
- ☐ Stop 3–4 times: standing still, throttle released, hold the brake lever for 3 seconds. A small jerk = a measurement.

5. The climb

phase 4

- ☐ Hardest climb available (the evening route, or a steep hill 2–3 times), full throttle where safe.
- ☐ Every 2–3 minutes: stop, stand still, hold the brake for 3 seconds.
- ☐ Aim: rear motor at 90–100 °C.
- ☐ Do not switch the scooter off after the climb.

Stop climbing if the motor temperature on the screen passes 110 °C (it shows the model) and ride gently. The current reduction starts by itself at 100 °C.

6. At the top: cooldown

phase 5 · 40 min

- ☐ Scooter on its stand, rear wheel off the ground (or keep the brake held the whole time). **Tell Claude** you are ready.
- ☐ Leave it alone for 40 minutes: no riding, no throttle, do not switch it off. One measurement a minute (small jerk each).
- ☐ Optional (phase 6): every 10 minutes read the IR thermometer on the tape and send Claude the time and value.

Time	IR shell °C	Time	IR shell °C

7. Afterwards

- ☐ Tell Claude you are done. Claude pulls the logs, fits the model and updates the script.