

q4590: after blocked feedback, a new query still requests infeasible motion

Recorded query 4 (saved packet 0003) | input states 17-24 | execution steps 25-32 | no new rollout


A T-like region and exact error location




B Eight attempted endpoints vs actual position



C Requested 1.213 m; actual 0 m; 8/8 collisions




Original RGB: state 24



Same position; yaw may change

Original RGB: state 32



Same position; yaw may change

Occupied
Safety margin
Reference route
Actual prefix / attempted endpoints
Actual position
T-like detector center
Branch bearing (not a path)
Saved T-like exposure radius