
Signal A
Signal B
Signal C
Signal D
Signal E
Normal stress
Coulomb shear stress
Fault density
Faulting
Fault slip tendency
Fault dilation tendency
Dilation
Temperature
Distance from faults
Fault curvature
Fault intersection density
0.0
0.5
1.0