

PT. HANDAL PRIMA RAHAYU

Supplier, Mechanical Part Recondition & Manufacturing

Address II 500 November Stage II 7000 5002, Workshop II Governian No.57 November Sage

Second Sage and Selected and Action of the Ac


Tangerang Selatan, 02 Januari 2023 Yth, PT ADNYANA

TANDA TERIMA NO. 001/TT/HPR/I/2023

Harap diterima dengan baik Dokumen/Barang/Invoice tersebut dibawah ini:

Banyaknya	Nama Dokumen/Barang/Ja	sa · · · · · · · · · · · · · · · · · · ·
2 Lbr	Kwitansi No. 001/KW/HPR/I/2022 (Rp. 221.889.000,00)	
2 Lbr	Faktur No. 001/INV/HPR.A/I/2023	
2 Lbr	Faktur Pajak	
3 Lbr	PH No. 183A/PH/HPR.A/XII/2022	
3 Lbr	PO No. 411/BB/CO/ADY/1222	
22 Lbr	Report Pekerjaan	
3 Lbr	Surat Jalan PT Handal Prima Rahayu	
2 Lbr	Surat Jalan Kapal	
3 Lbr	Surat Izin Barang Masuk PT. SMI	
2 Lbr	Surat Jalan Keluar PT. SMI	
	Spare Part Kapal MV. Bulk Batavia	
-	Pite (c. At-I	

Diterima Oleh,





Address, Jl. SDI Rawa Mekar Jaya RT/RW.005,002, Workshop Jl. Clater Raya No.57 Rawa Mekar Jaya Serpong Tangerang Selatan Banten Telp.021-75676100-E-mail: pt.handaiprimarahayu@gmail.com

SUDAH DITERIMA DARI BANYAK UANG

: PT. Adnyana

: Dua Ratus Dua Puluh Satu Juta Delapan Ratus Delapan Puluh Sembilan Ribu Rupiah

UNTUK PEMBAYARAN

: REPAIR GEAR BOX

1. Repair Gear Box Provision Crane, gty 1 Unit

Rewinding Electromotor Gearbox Provision Crane 4kw; 1450 Rpm, qty 1 Unit

3. Repair Slewing Bearing Dimensi Od 1060 ld 778 Lg 90 mm, gty 1 Pcs

4.Repair Unit Blower Motor & Casing For Tunnel, qty 1 Unit.

5. Repair Hydraulic Lifeboat, qty 2 Pcs

6.Rewinding Electromotor Fan Air Draft Motor Boller 10 H; 300 Rpm, gty 1 Unit. 7. Rewinding Electromotor Wiper Window Of Bridge 1 Hp: 1500 Rpm, gty 1 Unit.

8.Fabrikasi Hight Pressure For Hydraulic Jack Hatch Cover, qtv 15 Pcs 9.Replacement Double Napple 1/2" BSP For Hydraulic Jack Hatch Cover, qtv 5 Pcs 10.Replacement Elbow Nepple 3/4" BSP For Hydraulic Jack Hatch Cover, qtv 5 Pcs 11. Replacement Seal Kit For Hydraulic Jack HC SN 95/85-155, gty 15 Pcs

Spare part kapal MV Bulk Batavia : Faktur Nomor, 001/INV/HPR.A/I/2023

: PO Nomor: 411/BB/CO/ADY/1222

221,889,000.00

TRANSFER.

BANK CAB

: BANK SYARIAH INDONESIA : BUMI SERPONG DAMAI : PT HANDAL PRIMA RAHAYU

A/N REK NO

: 9146 294 530

lanuari 2023 Tangeran Hormaj

HANDAL PRIMA R

ADB4AAKX085894621



Supplier, Mechanical Part Recondition & Manufacturing

Date

: Tangerang Selatan, 02 Januari 2023

Nomor

: 001/INV/HPR.A/1/2023

Perihal

: Faktur

Kepada

PT. ADNYANA

Menara Kadin Indonesia (20 th Floor) HL. HR Rasuna Sald Blok X-5 Kav. 2 & 3 Kuningan, Jakarta 12950, Indonesia

	Unit	Qty	Unit Price (IDR)	Total Amount (IDR)
REPAIR GEAR BOX				
Repair Gear Box Provision Crane	Unit	1	37,450,000.00	37,450,000.00
Rewinding Electromator Gearbox Provision Crane 4kw; 1450 Rpm	Unit	1	8,500,000.00	8,500,000.00
Repair Slewing Bearing Dimensi Od 1060 Id 779 Lg 90 mm	Pcs	1	42,000,000.00	42,000,000.00
Repair Unit Blower Motor & Casing For Tunnel	Unit	1	33,000,000.00	33,000,000.00
Repair Hydraulic Lifeboat	Pcs	2	8,600,000.00	17,200,000.0
Rewinding Electromotor Fan Air Draft Motor Boiler 10 H; 300 Rpm	Unit	1 =	7,300,000.00	7,300,000.0
Rewinding Electromator Wiper Window Of Bridge 1 Hp: 1500 Rpm	Unit	i	2,200,000.00	2,200,000.0
Fabrikasi Hight Pressure For Hydraulic Jack Hatch Cover	Pcs	15	1,600,000.00	24,000,000.0
Replacement Double Napple 1/2" BSP For Hydraulic Jack Hatch Cove	Pcs	5	450,000.00	2,250,000.0
Replacement Elbow Nepple 3/4" BSP For Hydraulic Jack Hatch Cover	Pcs	5	550,000.00	2,750,000.0
Replacement Seal Kit For Hydraulic Jack HC SN 95/85-155	Pcs	15	1,550,000.00	23,250,000.0
Note: PO NO. 411/BB/CO/ADY/1222 VESSEL MV. BULK BATAVIA				
ital Int				199,900,000.00
	VESSEL MV. BULK BATAVIA			

Terbilang : # Dua Ratus Dua Puluh Satu Juta Delapan Ratus Delapan Puluh Sembilan Ribu Ruplah #

Transfer;

ACC

914 629 4530

BANK

: BANK SYARIAH INDONESIA

CAB

: BUMI SERPONG DAMAI

AN

: PT HANDAL PRIMA RAHAYU

PT. HANDAL PE ndal Prima Rahayu Rudi Hart

Address, Jl. SDI Rawa Mekar Jaya, Rt. 005 RW. 002, Rawa Mekar Jaya- Serpong Workshop: II. Clater Raya No.57, Rawa Mekar Jaya- Serpong - Tangerang Selatan - Banten - 15318 Telp.021-75676100-E-mail: pt.handalprimarahayu@gmail.com

Faktur Pajak

Kode dan Nomor Seri Faktur Pajak: 011.003-23.47501637

Pengusaha Kena Pajak

Nama: PT HANDAL PRIMA RAHAYU

Alamat : JL SDI RAWA MEKAR JAYA RT 005 RW 002 , KOTA TANGERANG SELATAN

NPWP: 94.277.529.7-411.000

Pembeli Barang Kena Pajak / Penerima Jasa Kena Pajak

Nama: PT. ADNYANA

Alamat : GEDUNG MENARA KADIN INDONESIA LANTAI 20 BLOK B,C, DAN D, JALAN H.R. RASUNA SAID Blok X-5

KAV. 2 & 3 No.- RT:008 RW:003 Kel.KUNINGAN TIMUR Kec.SETIABUDI Kota/Kab.JAKARTA SELATAN DKI

JAKARTA 12950

NPWP: 01.002.939.5-062.000

No.	Nama Barang Kena Pajak / Jasa Kena Pajak	Harga Jual/Penggantian/Uang Muka/Termin
1	REPAIR GEARBOX PROVISION CRANE Rp 37.450.000 x 1	37.450.000,00
2	REWINDING ELECTROMOTOR GEARBOX PROVISION CRANE 4 KW; 1450 RPM Rp 8.500.000 x 1	8.500.000,00
3	REPAIR SLEWING BEARING DIMENSI OD 1060 ID 778 LG 90 MM Rp 42.000.000 x 1	42.000.000,00
4	REPAIR UNIT BLOWER MOTOR & CASING FOR TUNNEL Rp 33.000.000 x 1	33.000.000,00
5	REPAIR HYDRAULIC LIFEBOAT Rp 8.600.000 x 2	17.200.000,00
6	REWINDING ELECTROMOTOR FAN AIR DRAFT MOTOR BOILER 10 HP; 3000 RPM Rp 7.300.000 x 1	7.300.000,00
7	REWINDING ELECTROMOTOR WIPER WINDOW OF BRIDGE 1HP; 1500 RPM Rp 2.200.000 x 1	2.200.000,00
8	FABRIKASI HIGH PRESSURE FOR HYDRAULIC JACK HATCH COVE Rp 1.600.000 x 15	24.000.000,00
9	REPLACEMENT DOUBLE NEPPLE 1/2" BSP FOR HYDRAULIC JACK HATCH COVER Rp 450.000 x 5	2.250.000,00
10	REPLACEMENT ELBOW NEPPLE 3/4" BSP FOR HYDRAULIC JACK HATCH COVER Rp 550.000 x 5	2.750.000,00
11	REPLACEMENT SEAL KIT FOR HYDRAULIC JACK HC SN 95/85-155 Rp 1.550.000 x 15	23.250.000,00

Harga Jual / Penggantian	199.900.000,00
Dikurangi Potongan Harga	0,00
Dikurangi Uang Muka	0,00
Dasar Pengenaan Pajak	199.900.000,00
Total PPN	21.989.000,00
Total PPnBM (Pajak Penjualan Barang Mewah)	0,00

Sesuai dengan ketentuan yang berlaku, Direktorat Jenderal Pajak mengatur bahwa Faktur Pajak ini telah ditandatangani secara elektronik sehingga tidak diperlukan tanda tangan basah pada Faktur Pajak ini.

KOTA TANGERANG SELATAN, 02 Januari 2023



RUDI HARTONO

SESUAI PO NO.411/BB/CO/ADY/1222 TGL.15/12/2022

Faktur Pajak

Kode dan Nomor Seri Faktur Pajak: 011.003-23.47501637

Pengusaha Kena Pajak

Nama: PT HANDAL PRIMA RAHAYU

Alamat : JL SDI RAWA MEKAR JAYA RT 005 RW 002 , KOTA TANGERANG SELATAN

NPWP: 94.277.529.7-411.000

Pembeli Barang Kena Pajak / Penerima Jasa Kena Pajak

Nama: PT. ADNYANA

Alamat : GEDUNG MENARA KADIN INDONESIA LANTAI 20 BLOK B,C, DAN D, JALAN H.R. RASUNA SAID Blok X-5

KAV. 2 & 3 No.- RT:008 RW:003 Kel.KUNINGAN TIMUR Kec.SETIABUDI Kota/Kab.JAKARTA SELATAN DKI

JAKARTA 12950

NPWP : 01 002 939 5-062 000

No.	Nama Barang Kena Pajak / Jasa Kena Pajak	Harga Jual/Penggantian/Uang Muka/Termin
1	REPAIR GEARBOX PROVISION CRANE Rp 37.450.000 x 1	37.450.000,00
2	REWINDING ELECTROMOTOR GEARBOX PROVISION CRANE 4 KW; 1450 RPM Rp 8.500.000 x 1	8.500.000,00
3	REPAIR SLEWING BEARING DIMENSI OD 1060 ID 778 LG 90 MM Rp 42.000.000 x 1	42.000.000,00
4	REPAIR UNIT BLOWER MOTOR & CASING FOR TUNNEL Rp 33.000.000 x 1	33.000.000,00
5	REPAIR HYDRAULIC LIFEBOAT Rp 8.600.000 x 2	17.200.000,00
6	REWINDING ELECTROMOTOR FAN AIR DRAFT MOTOR BOILER 10 HP; 3000 RPM Rp 7.300.000 x 1	7.300.000,00
7	REWINDING ELECTROMOTOR WIPER WINDOW OF BRIDGE 1HP; 1500 RPM Rp 2.200.000 x 1	2.200.000,00
8	FABRIKASI HIGH PRESSURE FOR HYDRAULIC JACK HATCH COVE Rp 1.600.000 x 15	24.000.000,00
9	REPLACEMENT DOUBLE NEPPLE 1/2" BSP FOR HYDRAULIC JACK HATCH COVER Rp 450.000 x 5	2.250.000,00
10	REPLACEMENT ELBOW NEPPLE 3/4" BSP FOR HYDRAULIC JACK HATCH COVER Rp 550.000 x 5	2.750.000,00
11	REPLACEMENT SEAL KIT FOR HYDRAULIC JACK HC SN 95/85-155 Rp 1.550.000 x 15	23.250.000,00

Harga Jual / Penggantian	199.900.000,00
Dikurangi Potongan Harga	0,00
Dikurangi Uang Muka	0,00
Dasar Pengenaan Pajak	199.900.000,00
Total PPN	21.989.000,00
Total PPnBM (Pajak Penjualan Barang Mewah)	0,00

Sesuai dengan ketentuan yang berlaku, Direktorat Jenderal Pajak mengatur bahwa Faktur Pajak ini telah ditandatangani secara elektronik sehingga tidak diperlukan tanda tangan basah pada Faktur Pajak ini.

KOTA TANGERANG SELATAN, 02 Januari 2023



RUDI HARTONO

SESUAI PO NO.411/BB/CO/ADY/1222 TGL.15/12/2022



Supplier, Mechanical Part Recondition & Manufacturing

Date : Tangerang Selatan, 13 Desember 2022

Nomor : 183A/PH/HPR.A/XII/2022 Hal : Penawaran Harga

Kepada Yth, **PT. Adnyana** Vessel MV Bulk Batavia

Up. Bapak Eko

Dengan Hormat,

Berikut ini kami sampaikan informasi harga perihal Repair, Fabrikasi & Replacement Spare Part MV Bulk Batavia, sebagai berikut :

NO.	ITEM DESCRIPTION Repair Gearbox Provision Crane		UNIT	Unit Price (IDR)	Sub. Total (IDR) 37,450,000
1			Unit	37,450,000	
	Scope of work :				
	a. Cleaning & pre inspection				
	b. Undercutt, welding, metal spray area bearing,				
	machining shaft dia. 80 x Lg. 280 mm				
	c. Fabrikasi gear od 142 id 75 lg 95 mm, mat. VCN				
	d. Hardeness gear				
	e. Replacement bearing 22212 (2 pcs), & 6212 (2 Pcs)				
	f. Replacement oil seal 60 x 110 x 12 (1 pc) &				
	g. 80 x 110 x 13 (1 Pc)				
	h. Replacement oring id 285 x t 3 mm (2 Pcs),				
	id 240 x t 3 mm (1 Pc) & id 140 x t 3,2 mm (1 Pc)				
	i. Replacement bolt & nut (1 Lot)				
	j. Assembling				
	k. Final inspection & painting				
	I Delivery				
2	Rewinding Elctromotor Gearbox Provision Crane	1	Unit	8,500,000	8,500,000
	4 Kw; 1450 Rpm				
	Scope of work :				
	a. Cleaning & pre inspection				
	b. Merger test before repair				
	c. Cleaning & pre inspection				
	d. Rewinding proses, material kawat hellenic				
	e. Round out / alignment shaft rotor				
	f. Sirlak main rotor				
	g. Replacement bearing 6307 (2 pcs)				
	h. Assembling				
	i. Merger test after repair				
	j. Final inspection & Painting				
	k. Delivery				

Address. Jl. SDI Rawa Mekar Jaya Workshop.Jl.Ciater Raya No.57 Rawa Mekar Jaya Serpong Tangerang Selatan Banten Telp.021-75676100-E-mail: pt.handalprimarahayu@gmail.com



Supplier, Mechanical Part Recondition & Manufacturing

NO.	ITEM DESCRIPTION	QTY	UNIT	Unit Price (IDR)	Sub. Total (IDR)	
3	Repair Slewing Bearing	1	Pc	42,000,000	42,000,000	
	Dimensi Od 1060 Id 778 Lg 90 mm					
	Scope of work:					
	a. Cleaning & pre inspection					
	b. Pembongkaran roller gear					
	c. Welding proses					
	d. Skimming area hole roller bearing Od 41,2 mm					
	e. Replacement roller pin dia 41,2 (65 Pcs) f. Assembling					
	g. Final inspection & painting					
	h. Delivery					
4	Repair Unit Blower Motor and Casing For Tunnel	1	Unit	33,000,000	33,000,000	
	Scope of work:					
	a. Cleaning & pre inspection					
	b. Fabrikasi housing od 417 id 405 p 500 mm, mat.					
	c. mild steel					
	d. Fabrikasi saringan housing, mat. wire mesh od 700					
	e. id 417 mm					
	f. Fabrikasi dudukan elmot p 130 l 100 t 30 mm, mat.					
370	mild steel					
	g. Rewinding Electromotor 3 Hp; 3000 Rpm					
	h. Replacement bearing 6205 (2 pcs) elmot					
	i. Welding, machining & dynamic balancing impeller blower					
	j. Metal spray & machining cover bearing elmot (1 Pc)					
	k. Assembling & final inspection					
	I. Painting & delivery					
5	Repair Hydraulic Lifeboat	2	Pcs	8,600,000	17,200,000	
	- Hardchrome Cylinder Rod Lifeboat					
10-17-1	Dimensi Dia 90 x Lg 2655 mm					
	Scope of work :					
	a. Cleaning & pre inspection					
	b. Undercutt, thick 0,30 mm					
	c. Welding proses					
	d. Machinig proses					
	e. Hardchrome process, thicknes 0,30 mm					
-71-2	f. Grinding diameter area					
	g. Poleshing process assembling					
	i. Final inspection dimension	1			1/4	
	j. Delivery					
6	Rewinding Electromotor Fan Air Draft Motor Boiler	1	Unit	7,300,000	7,300,000	
•	10 Hp; 3000 Rpm			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	1,,300	
	Scope of work :					
	a. Cleaning & pre inspection					
	b. Merger test before repair					
	c. Cleaning & pre inspection					
	S. S.SEIMING & P. C. M.OPCCOOM	1				

Address. Jl. SDI Rawa Mekar Jaya Workshop.Jl.Ciater Raya No.57 Rawa Mekar Jaya Serpong Tangerang Selatan Banten Telp.021-75676100-E-mail: <u>pt.handalprimarahayu@amail.com</u>



Supplier, Mechanical Part Recondition & Manufacturing

NO.	ITEM DESCRIPTION	QTY	UNIT	Unit Price (IDR)	Sub. Total (IDR)
	d. Rewinding proses, material kawat hellenic				
	e. Round out / alignment shaft rotor				
	f. Sirlak main rotor				
	g. Replacement bearing 6205 (2 pcs)				
	h. Assembling				
	i. Merger test after repair				
	j. Final inspection & Painting				
	k. Delivery				
7	Rewinding Electromotor Wiper Window Of Bridge	1	Unit	2,200,000	2,200,000
	1 Hp; 1500 Rpm				, ,
	Scope of work:				
	a. Cleaning & pre inspection				
	b. Merger test before repair				
	c. Cleaning & pre inspection				
	d. Rewinding proses, material kawat hellenic				
	e. Round out / alignment shaft rotor				
	f. Sirlak main rotor				
	g. Replacement bearing 6000 (2 pcs)				
	h. Assembling				
	i. Merger test after repair				
	j. Final inspection & Painting				
	k. Delivery				
8	Fabrikasi High Pressure For Hyraulic Jack Hatch Cover	15	Pcs	1,600,000	24,000,000
9	Replacement Double Nepple 1/2" BSP For Hyraulic Jack	5	Pcs	450,000	2,250,000
	Hatch Cover				
10	Replacement Elbow Nepple 3/4" BSP For Hyraulic Jack	5	Pcs	550,000	2,750,000
	Hatch Cover				, , , , , , , , , , , , , , , , , , , ,
11	Replacement Seal Kit For Hydraulic Jack HC SN 95/85-155	15	Pcs	1,550,000	23,250,000
				Subtotal	199,900,000
Terb	ilang : # Seratus Sembilan Puluh Sembilan Juta Sembilan Rati	us Ribu R	Rupiah #	PPN	
	or angeneral and an anti-section of the section of			Total	199,900,000

Keterangan:

Lama pekerjaan

10 (Sepuluh) hari kerja setelah PO

Pembayaran

2 (Dua) minggu setelah serah terima invoice

Garansi

: 3 (Tiga) bulan setelah serah terima

Note

: Penawaran Harga berlaku 10 (sepuluh) hari kerja

Demikian surat penawaran Repair, Fabrikasi & Replacement Spare Part MV Bulk Batavia, ini kami sampaikan, atas perhatian dan kerjasamanya kami ucapkan terima kasih.

Hormat kami,
PT. HANDA PRIMA MHAYU

INdinationo
Hp. 081283656333

Diterima dan disetujui,

() Nama dan Cap Perusahaan

Address. Jl. SDI Rawa Mekar Jaya Workshop.Jl.Ciater Raya No.57 Rawa Mekar Jaya Serpong Tangerang Selatan Banten Telp.021-75676100-E-mail: <u>pt.handalprimarahayu@gmail.com</u>



P.E. Adnyana

PURCHASE ORDER

Head Office: Menara Kadin Indonesia (20th Floor), Jl. H.R. Rasuna Said Blok X-5 Kav. 2 & 3 Kuningan, Jakarta 12950, Indonesia

Phone: (62-21) 5227220 Fax: (62-21) 5227221 - 5274770 E-mail: enquiries@andhika.com

ORDER TO:

HARTONO

PT. HANDAL PRIMA RAHAYU Mr. RUDI

SHIP TO:

PT. ADNYANA

MV. BULK BATAVIA

PO DATE

PO NO

15 Dec 2022 | 411/BB/CO/ADY/1222

SUBJECT:

REPAIR GEARBOX

No	P/N	Description	QTY	Unit Price	Amount
		Repair Gearbox		RP	RP
1		Bonair Goarboy Broyleion Crano	1 UNIT	37.450.000	27 450 000
1		Repair Gearbox Provision Crane Scope of work:	1 UNII	37.430.000	37.450.000
		a. Cleaning & pre inspection			
		b. Undercutt, welding, metal spray area bearing,			
		machining shaft dia. 80 x Lg. 280 mm			
		c. Fabrikasi gear od 142 id 75 lg 95 mm, mat. VCN			
		d. Hardeness gear			
		e. Replacement bearing 22212 (2 pcs) & 6212 (2 pcs)			
		f. Replacement oil seal 60 x 110 x 12 (1 pc) &			
		g. 80 x 110 x 13 (1 Pc)			
		h. Replacement oring id 285 x t 3 mm (2 Pcs), id			
		240 x t 3 mm (1 Pc) & id 140 x t 3,2 mm (1 Pc)			
		i. Replacement bolt & nut (1 Lot)			
		j. Assembling			
		k. Final inspection & painting			
		I. Delivery			
2		Rewinding Elctromotor Gearbox Provision Crane	1 UNIT	8.500.000	8.500.000
		4 Kw; 1450 Rpm			
		Scope of work :			
		a. Cleaning & pre inspection			
		b. Merger test before repair			
		c. Cleaning & pre inspection			
		d. Rewinding proses, material kawat hellenic			
		e. Round out / alignment shaft rotor			
		f. Sirlak main rotor			
		g. Replacement bearing 6307 (2 pcs)			
		h. Assembling			
		i. Merger test after repair			
		j. Final inspection & Painting			
		k. Delivery			
3		Repair Slewing Bearing	1 PC	42.000.000	42.000.000
		Dimensi Od 1060 ld 778 Lg 90 mm			
		Scope of work :			
		a. Cleaning & pre inspection			
		b. Pembongkaran roller gear			
		c. Welding proses			



P.E. Adnyana

PURCHASE ORDER

Head Office: Menara Kadin Indonesia (20th Floor),
Jl. H.R. Rasuna Said Blok X-5 Kav. 2 & 3
Kuningan, Jakarta 12950, Indonesia

Phone: (62-21) 5227220 Fax: (62-21) 5227221 - 5274770 E-mail: enquiries@andhika.com

ORDER TO:
PT. HANDAL
PRIMA RAHAYU
Mr. RUDI
HARTONO

SHIP TO: PT. ADNYANA MV. BULK BATAVIA

PO DATE	PO NO
15 Dec 2022	411/BB/CO/ADY/1222

SUBJECT:REPAIR GEARBOX

No	P/N	Description	QTY	Unit Price	Amount
		d. Skimming area hole roller bearing Od 41,2 mm			
		e. Replacement roller pin dia 41,2 (65 Pcs)			
		f. Assembling			
		g. Final inspection & painting			
		h. Delivery			
4		Repair Unit Blower Motor and Casing For Tunnel	1 UNIT	33.000.000	33.000.000
		Scope of work :			
		a. Cleaning & pre inspection			
		b. Fabrikasi housing od 417 id 405 p 500 mm, mat.			
		c. mild steel			
		d. Fabrikasi saringan housing, mat. wire mesh od 700			
		e. id 417 mm			
		f. Fabrikasi dudukan elmot p 130 l 100 t 30 mm, mat.			
		g. Rewinding Electromotor 3 Hp; 3000 Rpm			
		h. Replacement bearing 6205 (2 pcs) elmot			
		i. Welding, machining & dynamic balancing impeller			
		j. Metal spray & machining cover bearing elmot (1 Pc)			
		k. Assembling & final inspection			
		I. Painting & delivery			
5		Repair Hydraulic Lifeboat	2 PCS	8.600.000	17.200.000
		- Hardchrome Cylinder Rod Lifeboat			
		Dimensi Dia 90 x Lg 2655 mm			
		Scope of work :			
		a. Cleaning & pre inspection			
		b. Undercutt, thick 0,30 mm			
		c. Welding proses			
		d. Machinig proses			
		e. Hardchrome process, thicknes 0,30 mm			
		f. Grinding diameter area			
		g. Poleshing process assembling			
		i. Final inspection dimension			
		j. Delivery			
6		Rewinding Electromotor Fan Air Draft Motor Boiler	1 UNIT	7.300.000	7.300.000
		10 Hp; 3000 Rpm			
		Scope of work : (Sesuai Quotation)			
		a. Cleaning & pre inspection			
		b. Merger test before repair			
		c. Cleaning & pre inspection			
		d. Rewinding proses, material kawat hellenic			



P.E. Adnyana

PURCHASE ORDER

Head Office: Menara Kadin Indonesia (20th Floor),
Jl. H.R. Rasuna Said Blok X-5 Kav. 2 & 3
Kuningan, Jakarta 12950, Indonesia

Phone: (62-21) 5227220 Fax: (62-21) 5227221 - 5274770 E-mail: enquiries@andhika.com

ORDER TO:
PT. HANDAL
PRIMA RAHAYU
Mr. RUDI
HARTONO

SHIP TO: PT. ADNYANA MV. BULK BATAVIA
 PO DATE
 PO NO

 15 Dec 2022
 411/BB/CO/ADY/1222

SUBJECT:

REPAIR GEARBOX

No	P/N	Description	QTY	Unit Price	Amount
		e. Round out / alignment shaft rotor			
		f. Sirlak main rotor			
		g. Replacement bearing 6205 (2 pcs)			
		h. Assembling			
		i. Merger test after repair			
		j. Final inspection & Painting			
		k. Delivery			
7		Rewinding Electromotor Wiper Window Of Bridge	1 UN	IIT 2.200.000	2.200.00
		1 Hp; 1500 Rpm			
		Scope of work:			
		a. Cleaning & pre inspection			
		b. Merger test before repair			
		c. Cleaning & pre inspection			
		d. Rewinding proses, material kawat hellenic			
		e. Round out / alignment shaft rotor			
		f. Sirlak main rotor			
		g. Replacement bearing 6000 (2 pcs)			
		h. Assembling			
		i. Merger test after repair			
		j. Final inspection & Painting			
		k. Delivery			
8		Fabrikasi High Pressure For Hyraulic Jack Hatch Cover	15 PC	S 1.600.000	24.000.00
9		Replacement Double Nepple 1/2" BSP For Hyraulic Jack	5 PC	S 450.000	2.250.00
		Hatch Cover			
10		Replacement Elbow Nepple 3/4" BSP For Hyraulic Jack	5 PC	S 550.000	2.750.00
		Hatch Cover			
11		Replacement Seal Kit For Hydraulic Jack HC SN	15 PC	S 1.550.000	23.250.00
		95/85-155			
				Sub Total :	199.900.000
				Diagonat .	

Approved by,

Hari Joko Purnomo

James.

Defandra Putra

Sub Total : 199.900.000

Discount : 199.900.000

PPn: 21.989.000

Delivery Cost :
TOTAL: 221.889.000