



OPYR02 **OPYRO3**

File: Elytra.kicad_sch



Sensor Unit 1: BOSH AXL&GYRO + ST MAGNETOMETER + BOSH HUMIDITY

BMI323: 6.4KHz, SPI 10MHz LIS2MDL: 100Hz, SPI 10MHz



Sensor Unit 2: ST AXL&GYRO + BOSH BAROMETER + ST BAROMETER

LSM6DSO: 6.4KHz, I2C Fast Mode 400kHz, ADDR 0x6A BMP581: 400Hz, I2C Fast Mode Plus 1MHz, ADDR 0x46 LPS22DF: 200Hz, I2C Fast Mode Plus 1MHz, ADDR 0x5C

