PO Box 518 620 Applegate St. Philomath, OR 97370



(541) 929-5650 Fax (541) 929-5277 www.wetlabs.com

## **ECO CDOM Fluorometer Characterization Sheet**

Date: 4/26/2017 S/N: FLBBCD2K-4701

CDOM concentration expressed in ppb can be derived using the equation:

**CDOM (ppb) = Scale Factor \* (Output - Dark Counts)** 

Digital
Dark Counts
Scale Factor (SF)
0.0909 ppb/count
Maximum Output
Resolution
1.0 counts

Ambient temperature during characterization 23.0 °C

**Dark Counts:** Signal output of the meter in clean water with black tape over detector.

**SF:** Determined using the following equation:  $SF = x \div (output - dark counts)$ , where x is the concentration of the solution used during instrument characterization. SF is used to derive instrument output concentration from the raw signal output of the fluorometer.

Maximum Output: Maximum signal output the fluorometer is capable of.

Resolution: Standard deviation of 1 minute of collected data.

FLBBCD2K-4701.xls Revision S 10/4/07