## Subcontractor Protocol

## Morning - 8:00am

- 1. Come with clean uniform
- 2. Black Shoes
- 3. If Paining job bring changing clothes (for dirty jobs)
- 4. Make sure you have suits

5.

## Van Equipment Checklist

- 1. Driver arrive in the morning 8:00 AM
- 2. Driver Check the "Van Equipment Checklist" (lista de equipos)
- 3. **Driver** Let Supervisor know if anything missing (Give him list)
- 4. **Supervisor** If equipment missing in car ask <u>Field manager</u> to get stuff from the storage

5.