Nucleo serial mapping:

```
"Serial " TX PA09
"Serial " RX PA10

"Serial1" TX PA2
"Serial1" RX PA3

"Serial2" TX PC10
"Serial2" RX PC11
```

With my hardware modification (PC10 soldered to ST-Link RX and PC11 soldered to ST-Link TX) you can get "Arduino style" serial monitor without cables on "Serial2". At the moment it's not possible to set PC10/PC11 as "Serial" (would be more convenient)