
Box should measure 150mm square. Circles are 20mm in diameter.



Cut out square and position according to calibration program instructions.