
ZZ1 ■ These assemblies are ESD sensitive, ESD precautions shall be observed.

ZZ2 ■ These assemblies must be clean and free from flux and all contaminants. Use of no clean flux is not acceptable.


ZZ3 ■ These assemblies must comply with workmanship standards IPC-A-610 Class 2, unless otherwise specified.

ZZ4 ■ Indication provided for the D* components at their cathode side.
Assemble shunt part (SH-J1) on pins of J5.



COMPONENTS MARKED 'DNP' SHOULD NOT BE POPULATED.
ASSEMBLY VARIANT: 001

PCB VIEWED FROM TOP SIDE	BOARD #: BQ76952 SCD board	REV: A
TOP ASSEMBLY DRAWING	TID #: N/A	SVN REV: Not In VersionControl
	GENERATED : 17-04-2020 13:32:46	TEXAS INSTRUMENTS



COMPONENTS MARKED 'DNP' SHOULD NOT BE POPULATED.
ASSEMBLY VARIANT: 001

PCB VIEWED FROM BOTTOM SIDE	BOARD #: BQ76952 SCD board	REV: A
BOTTOM ASSEMBLY DRAWING	TID #: N/A	SVN REV: Not In VersionControl
	GENERATED : 17-04-2020 13:32:46	TEXAS INSTRUMENTS