



THREE TASKS



Pick & Place



Peg-in-hole



Screwdriving

9k Episodes | 27 Fault Types
UR3 and KUKA KR10

Collision with soft and rigid objects

Additional axis weight

Cable collision

Unstable
base

Hole
obstruction

External arm
disturbance