




Label Approval Process



1. Label has to meet Endries requirement on dimension.

Length: 4"~6" Width: 2"~4"

- 2. B has to meet A, and C has to be CODE 3 of 9.
- 3. Prod, QTY and LOT# must be successfully scanned on every label.
- 4. 3 pieces have to be scanned at least.



Label Approval Process

- 1. QA team members scan labels on suppliers who are responsible on.
- 2. QA team members notice suppliers that labels are approved.
- 3. All approvals are stored and managed in Taiwan folder at M driver.

