New Journal

- 1: Component.405_Laser_Power.Position = 100 2: pulsetime = 200
- 3: counter_2 = 1
- 4: counter_1 = 1 5: size_dilate = 0
- Total Regions = 0
- 6: Select Focus Device(Device Name = Leica Z Motor)
- 7: Start Continuous Focusing(0)