

[illegible]

Tegningsnummer	Egen kontrol værktøjed, Int	Welding control	Type	Antal	Vægt [kg]	Samlet vægt [kg]	Opkær	Maling	Læsning	Revision	Revision og dato	Revisions tekst	Tegnet af:	Overflade [m ²]	Samlet overflade [m ²]
G.8			3D (special)		0,0	0,0				0			ZLL	0,0	0,0
[d.1]			Drager IPE270 L= 4790	1	181,1	181,1				0			ZLL	5,2	5,2
[d.2]			Drager IPE270 L= 5300	1	200,0	200,0				0			ZLL	5,9	5,9
[d.3]			Drager IPE270 L= 5300	1	200,1	200,1				0			ZLL	5,8	5,8
[d.4]			Drager HEB360 L= 14962	5	2151,3	10756,6				0			ZLL	28,1	140,5
[d.5]			Drager HEB360 L= 14962	4	2172,6	8690,3				0			ZLL	28,5	114,0
[d.6]			Drager HEB360 L= 14962	1	2176,1	2176,1				0			ZLL	28,6	28,6
[d.7]			Drager HEB360 L= 14962	1	2179,1	2179,1				0			ZLL	28,6	28,6
[d.8]			Drager HEB360 L= 14962	1	2174,8	2174,8				0			ZLL	28,6	28,6
[d.9]			Drager HEB360 L= 14962	1	2172,3	2172,3				0			ZLL	28,5	28,5
[d.10]			Drager HEB360 L= 14962	1	2185,2	2185,2				0			ZLL	28,8	28,8
[d.11]			Drager HEB360 L= 14962	1	2194,9	2194,9				0			ZLL	29,0	29,0
[d.12]			Drager IPE400 L= 14810	1	991,7	991,7				0			ZLL	22,0	22,0
[d.13]			Drager IPE400 L= 14810	1	1001,5	1001,5				0			ZLL	22,2	22,2
[d.14]			Drager IPE270 L= 4780	1	179,0	179,0				0			ZLL	5,2	5,2
[d.15]			Drager IPE270 L= 4780	1	179,0	179,0				0			ZLL	5,2	5,2
[d.16]			Drager IPE270 L= 4780	1	179,0	179,0				0			ZLL	5,2	5,2
[d.17]			Drager IPE270 L= 4780	1	179,0	179,0				0			ZLL	5,2	5,2
[d.18]			Drager IPE270 L= 4780	1	179,0	179,0				0			ZLL	5,2	5,2
[d.19]			Drager IPE270 L= 4780	1	179,0	179,0				0			ZLL	5,2	5,2
[d.20]			Drager IPE270 L= 4780	1	179,7	179,7				0			ZLL	5,2	5,2
[d.21]			Drager IPE270 L= 4700	1	176,4	176,4				0			ZLL	5,1	5,1
[d.22]			Drager IPE270 L= 4700	1	177,1	177,1				0			ZLL	5,1	5,1
[d.23]			Drager IPE270 L= 4780	1	179,0	179,0				0			ZLL	5,2	5,2
[d.41]			Drager HEB360 L= 14962	1	2151,3	2151,3				0			ZLL	28,1	28,1
[f.1]			HSQ FL35*250 L= 4715	1	823,2	823,2				0			ZLL	12,7	12,7
[f.2]			HSQ FL35*250 L= 4715	1	823,8	823,8				0			ZLL	12,8	12,8
[f.3]			HSQ FL35*250 L= 4820	1	837,4	837,4				0			ZLL	12,9	12,9
[f.4]			HSQ FL35*250 L= 4820	1	837,4	837,4				0			ZLL	12,9	12,9
[f.5]			HSQ FL35*250 L= 4820	1	837,4	837,4				0			ZLL	12,9	12,9
[f.6]			HSQ FL35*250 L= 4820	1	837,4	837,4				0			ZLL	12,9	12,9
[f.7]			HSQ FL35*250 L= 4820	1	838,1	838,1				0			ZLL	12,9	12,9
[f.8]			HSQ FL35*250 L= 4820	1	838,9	838,9				0			ZLL	12,9	12,9
[f.9]			HSQ FL35*250 L= 4820	1	838,9	838,9				0			ZLL	12,9	12,9
[f.10]			HSQ FL35*250 L= 4820	1	843,3	843,3				0			ZLL	13,0	13,0
[f.11]			HSQ FL35*250 L= 4820	1	838,7	838,7				0			ZLL	13,0	13,0
[f.12]			HSQ FL35*250 L= 5020	1	870,5	870,5				0			ZLL	13,4	13,4
[f.13]			HSQ FL35*250 L= 5020	1	873,3	873,3				0			ZLL	13,5	13,5
[f.14]			Fladstål FL10*100 L= 150	2	2,0	3,9				0			ZLL	0,1	0,1
[f.15]			Fladstål FL10*100 L= 150	1	2,0	2,0				0			ZLL	0,1	0,1
[l.1]			Løsdele FL10*140 L= 170	4	1,9	7,5				0			ZLL	0,1	0,2

Tegningsnummer	Egen kontrol værktøds, Int	Welding control	Type	Antal	Vægt [kg]	Samlet vægt [kg]	Opkær	Maling	Lærning	Revision	Revision og dato	Revisions tekst	Tegnet af:	Overflade [m ²]	Samlet overflade [m ²]
[l.2]			Løsdele PL15*170 L= 600	2	11,1	22,1				0			ZLL	0,2	0,4
[l.3]			Løsdele FL12*170 L= 250	32	4,0	128,1				0			ZLL	0,1	3,0
[p.1]			Portomfatning RHS100X100X6 L= 2350	8	40,8	326,4				0			ZLL	0,9	7,6
[p.2]			Portomfatning RHS100X100X6 L= 1220	24	22,3	534,6				0			ZLL	0,5	12,5
[p.3]			Portomfatning RHS100X100X6 L= 4740	4	80,6	322,6				0			ZLL	1,9	7,4
[p.4]			Portomfatning RHS100X100X6 L= 3470	2	60,3	120,7				0			ZLL	1,4	2,8
[p.5]			Portomfatning RHS100X100X6 L= 2350	1	40,6	40,6				0			ZLL	0,9	0,9
[p.6]			Portomfatning RHS100X100X6 L= 3155	1	53,1	53,1				0			ZLL	1,2	1,2
[p.7]			Portomfatning RHS100X100X6 L= 2245	2	39,1	78,1				0			ZLL	0,9	1,8
[p.8]			Portomfatning RHS100X100X6 L= 2245	1	39,1	39,1				0			ZLL	0,9	0,9
[p.9]			Portomfatning RHS100X100X6 L= 2340	1	40,6	40,6				0			ZLL	0,9	0,9
[p.10]			Portomfatning RHS100X100X6 L= 2360	1	41,0	41,0				0			ZLL	0,9	0,9
[p.11]			Portomfatning L100*10 L= 1200	4	18,1	72,2				0			ZLL	0,5	1,9
[p.12]			Portomfatning RHS100X100X6 L= 4800	4	81,7	326,6				0			ZLL	1,9	7,5
[p.13]			Portomfatning RHS100X100X6 L= 2260	1	39,3	39,3				0			ZLL	0,9	0,9
[p.14]			Portomfatning RHS100X100X6 L= 2350	1	40,8	40,8				0			ZLL	0,9	0,9
[p.15]			Portomfatning RHS100X100X6 L= 2410	1	41,8	41,8				0			ZLL	1,0	1,0
[p.16]			Portomfatning RHS100X100X6 L= 2410	1	41,8	41,8				0			ZLL	1,0	1,0
[p.17]			Portomfatning RHS100X100X6 L= 4800	1	81,7	81,7				0			ZLL	1,9	1,9
[p.18]			Portomfatning RHS100X100X6 L= 3533	1	61,8	61,8				0			ZLL	1,4	1,4
[p.19]			Portomfatning RHS100X100X6 L= 3533	1	61,8	61,8				0			ZLL	1,4	1,4
[p.20]			Portomfatning RHS100X100X6 L= 3533	1	62,1	62,1				0			ZLL	1,4	1,4
[p.21]			Portomfatning RHS100X100X6 L= 2150	5	39,7	198,3				0			ZLL	0,9	4,6
[p.22]			Portomfatning RHS100X100X6 L= 4980	1	85,9	85,9				0			ZLL	2,0	2,0
[p.23]			Portomfatning RHS100X100X6 L= 2770	1	48,4	48,4				0			ZLL	1,1	1,1
[p.24]			Portomfatning RHS100X100X6 L= 2612	1	45,7	45,7				0			ZLL	1,1	1,1
[p.25]			Portomfatning RHS100X100X6 L= 2612	1	46,0	46,0				0			ZLL	1,1	1,1
[p.26]			Portomfatning RHS100X100X6 L= 2220	2	39,2	78,4				0			ZLL	0,9	1,8
[p.27]			Portomfatning RHS100X100X6 L= 4800	4	81,7	326,6				0			ZLL	1,9	7,5
[p.28]			Portomfatning RHS100X100X6 L= 3171	1	55,5	55,5				0			ZLL	1,3	1,3
[p.29]			Portomfatning RHS100X100X6 L= 2887	1	50,7	50,7				0			ZLL	1,2	1,2
[p.30]			Portomfatning RHS100X100X6 L= 3055	1	53,2	53,2				0			ZLL	1,2	1,2
[p.31]			Portomfatning RHS100X100X6 L= 2795	1	48,4	48,4				0			ZLL	1,1	1,1
[p.32]			Portomfatning RHS100X100X6 L= 1110	1	19,8	19,8				0			ZLL	0,5	0,5
[p.33]			Portomfatning RHS100X100X6 L= 3155	1	53,1	53,1				0			ZLL	1,2	1,2
[p.34]			Portomfatning RHS100X100X6 L= 3155	1	55,1	55,1				0			ZLL	1,3	1,3
[p.35]			Portomfatning RHS100X100X6 L= 3533	1	66,0	66,0				0			ZLL	1,6	1,6
[p.76]			Portomfatning RHS100X100X6 L= 2220	1	39,2	39,2				0			ZLL	0,9	0,9
[p.77]			Portomfatning RHS100X100X6 L= 2612	1	45,7	45,7				0			ZLL	1,1	1,1
[p.78]			Portomfatning RHS100X100X6 L= 3155	2	118,2	236,5				0			ZLL	2,8	5,5
[p.80]			Portomfatning RHS100X100X6 L= 4150	1	71,8	71,8				0			ZLL	1,6	1,6

DS Tekla Tegningsliste

Tegningsnummer	Egen kontrol værktøds, Int	Welding control	Type	Antal	Vægt [kg]	Samlet vægt [kg]	Opkær	Maling	Læsning	Revision	Revision og dato	Revisions tekst	Tegnet af:	Overflade [m ²]	Samlet overflade [m ²]
[s.1]			Søjle RHS150X150X8 L= 7100	7	300,5	2103,6				0			ZLL	5,1	35,6
[s.2]			Søjle RHS180X180X10 L= 7850	1	389,4	389,4				0			ZLL	5,8	5,8
[s.3]			Søjle RHS150X150X8 L= 7180	1	303,2	303,2				0			ZLL	5,1	5,1
[s.4]			Søjle RHS150X150X8 L= 7180	1	289,3	289,3				0			ZLL	4,9	4,9
[s.5]			Søjle RHS180X180X10 L= 7850	1	400,9	400,9				0			ZLL	6,1	6,1
[s.6]			Søjle RHS150X150X8 L= 7180	1	289,3	289,3				0			ZLL	4,9	4,9
[s.7]			Søjle RHS180X180X10 L= 6600	1	338,3	338,3				0			ZLL	5,1	5,1
[s.8]			Søjle RHS180X180X10 L= 6600	1	371,3	371,3				0			ZLL	5,9	5,9
[s.9]			Søjle RHS180X180X10 L= 6600	1	346,0	346,0				0			ZLL	5,2	5,2
[s.10]			Søjle RHS180X180X10 L= 6600	1	344,0	344,0				0			ZLL	5,2	5,2
[s.11]			Søjle RHS180X180X10 L= 6600	1	367,7	367,7				0			ZLL	5,8	5,8
[s.12]			Søjle RHS180X180X10 L= 6600	2	333,5	667,1				0			ZLL	5,0	9,9
[s.13]			Søjle RHS180X180X10 L= 6600	3	333,5	1000,6				0			ZLL	5,0	14,9
[s.14]			Søjle RHS180X180X10 L= 6600	1	354,0	354,0				0			ZLL	5,4	5,4
[s.15]			Søjle RHS180X180X10 L= 6600	1	320,4	320,4				0			ZLL	4,6	4,6
[s.16]			Søjle RHS180X180X10 L= 6600	1	329,4	329,4				0			ZLL	4,9	4,9
[s.17]			Søjle RHS180X180X8 L= 7225	1	290,5	290,5				0			ZLL	5,2	5,2
[s.18]			Søjle RHS180X180X8 L= 8450	1	359,7	359,7				0			ZLL	6,3	6,3
[s.19]			Søjle RHS180X180X8 L= 7225	1	302,4	302,4				0			ZLL	5,4	5,4
[s.20]			Søjle RHS180X180X10 L= 6600	1	326,6	326,6				0			ZLL	4,8	4,8
[s.21]			Søjle RHS100X100X6 L= 2465	4	43,9	175,8				0			ZLL	1,0	4,0
[s.22]			Søjle RHS100X100X6 L= 2465	2	43,9	87,9				0			ZLL	1,0	2,0
[s.23]			Søjle RHS100X100X6 L= 2465	2	43,9	87,9				0			ZLL	1,0	2,0
[s.24]			Søjle RHS150X150X8 L= 6504	1	219,9	219,9				0			ZLL	3,7	3,7
[s.25]			Søjle RHS100X100X6 L= 2465	1	63,9	63,9				0			ZLL	1,4	1,4
[s.26]			Søjle RHS150X150X8 L= 3715	1	156,0	156,0				0			ZLL	2,6	2,6
[s.27]			Søjle RHS150X150X8 L= 3715	1	153,5	153,5				0			ZLL	2,6	2,6
[s.28]			Søjle RHS150X150X8 L= 3995	1	165,2	165,2				0			ZLL	2,8	2,8
[s.29]			Søjle RHS150X150X8 L= 3995	1	162,9	162,9				0			ZLL	2,7	2,7
[s.30]			Søjle RHS180X180X10 L= 3865	1	188,7	188,7				0			ZLL	2,9	2,9
[s.31]			Søjle RHS180X180X10 L= 3865	1	190,6	190,6				0			ZLL	3,0	3,0
[s.32]			Søjle RHS180X180X10 L= 3865	1	192,3	192,3				0			ZLL	3,0	3,0
[s.33]			Søjle RHS180X180X10 L= 3865	1	193,1	193,1				0			ZLL	3,0	3,0
[s.34]			Søjle RHS100X100X6 L= 3107	1	68,2	68,2				0			ZLL	1,4	1,4
[s.35]			Søjle RHS150X100X6 L= 3107	1	78,1	78,1				0			ZLL	1,6	1,6
[s.36]			Søjle RHS100X100X6 L= 2465	1	45,4	45,4				0			ZLL	1,0	1,0
[s.54]			Søjle RHS150X150X8 L= 7100	1	300,5	300,5				0			ZLL	5,1	5,1
[s.55]			Søjle RHS150X150X8 L= 7180	1	303,2	303,2				0			ZLL	5,1	5,1
[s.56]			Søjle RHS100X100X6 L= 2465	3	43,9	131,8				0			ZLL	1,0	3,0
[x.1]			Vind-X RHS100X100X6 L= 4787	4	84,3	337,3				0			ZLL	1,9	7,6
[x.2]			Vind-X RHS100X100X6 L= 4704	2	82,9	165,8				0			ZLL	1,9	3,7

Tegningsnummer	Egen kontrol værktøds, Int	Welding control	Type	Antal	Vægt [kg]	Samlet vægt [kg]	Opkær	Maling	Læsning	Revision	Revision og dato	Revisions tekst	Tegnet af:	Overflade [m ²]	Samlet overflade [m ²]
[x.3]			Vind-X RHS100X100X6 L= 4780	1	86,8	86,8				0			ZLL	2,0	2,0
[x.4]			Vind-X RHS100X100X6 L= 4780	1	86,8	86,8				0			ZLL	2,0	2,0
[x.5]			Vind-X RHS100X100X6 L= 4780	1	88,4	88,4				0			ZLL	2,0	2,0
[x.6]			Vind-X RHS100X100X6 L= 4780	12	83,1	997,7				0			ZLL	1,9	22,5
[x.7]			Vind-X RHS100X100X6 L= 4690	1	85,3	85,3				0			ZLL	1,9	1,9
[x.8]			Vind-X RHS100X100X6 L= 4690	1	85,3	85,3				0			ZLL	1,9	1,9
[x.9]			Vind-X RHS100X100X6 L= 4690	2	81,6	163,2				0			ZLL	1,8	3,7
[x.10]			Vind-X RHS100X100X6 L= 4720	1	82,1	82,1				0			ZLL	1,9	1,9
[x.11]			Vind-X RHS100X100X6 L= 4720	1	82,1	82,1				0			ZLL	1,9	1,9
[x.12]			Vind-X RHS120X120X10 L= 5240	1	170,5	170,5				0			ZLL	2,5	2,5
[x.13]			Vind-X RHS120X120X8 L= 9270	1	249,8	249,8				0			ZLL	4,4	4,4
[x.14]			Vind-X RHS120X120X8 L= 9270	1	248,2	248,2				0			ZLL	4,3	4,3
[x.15]			Vind-X RHS120X120X8 L= 9270	6	247,4	1484,5				0			ZLL	4,3	25,8
[x.16]			Vind-X RHS100X100X6 L= 4791	1	84,4	84,4				0			ZLL	1,9	1,9
[x.17]			Vind-X RHS100X100X6 L= 4808	1	84,7	84,7				0			ZLL	1,9	1,9
[x.18]			Vind-X D30 L= 2455	4	19,8	79,3				0			ZLL	0,4	1,6
[x.19]			Vind-X D30 L= 5374	2	31,3	62,6				0			ZLL	0,6	1,2
[x.20]			Vind-X D30 L= 6100	4	35,1	140,5				0			ZLL	0,7	2,6
[x.21]			Vind-X D30 L= 5582	1	32,4	32,4				0			ZLL	0,6	0,6
[x.22]			Vind-X D30 L= 5927	1	34,2	34,2				0			ZLL	0,6	0,6
[x.23]			Vind-X D30 L= 6723	4	38,4	153,7				0			ZLL	0,7	2,9
[x.24]			Vind-X D30 L= 6772	4	38,7	154,8				0			ZLL	0,7	2,9
[x.25]			Vind-X D30 L= 6667	4	38,1	152,5				0			ZLL	0,7	2,8
[x.26]			Vind-X D30 L= 5287	2	34,8	69,7				0			ZLL	0,7	1,3
[x.27]			Vind-X D30 L= 5499	1	31,9	31,9				0			ZLL	0,6	0,6
[x.28]			Vind-X D30 L= 5800	1	33,5	33,5				0			ZLL	0,6	0,6
[x.29]			Vind-X RHS100X100X6 L= 4740	1	86,1	86,1				0			ZLL	1,9	1,9
[x.30]			Vind-X RHS100X100X6 L= 4935	1	84,9	84,9				0			ZLL	1,9	1,9
[x.31]			Vind-X RHS100X100X6 L= 4910	6	84,5	507,0				0			ZLL	1,9	11,4
[x.32]			Vind-X RHS100X100X6 L= 4765	1	82,0	82,0				0			ZLL	1,9	1,9
[x.33]			Vind-X D30 L= 6714	2	38,4	76,8				0			ZLL	0,7	1,4
[x.34]			Vind-X D30 L= 6786	1	38,8	38,8				0			ZLL	0,7	0,7
[x.35]			Vind-X D30 L= 6774	1	38,7	38,7				0			ZLL	0,7	0,7
[x.60]			Vind-X RHS100X100X6 L= 4788	12	84,3	1011,9				0			ZLL	1,9	22,8
[x.61]			Vind-X RHS100X100X6 L= 4780	2	83,1	166,3				0			ZLL	1,9	3,8
[x.62]			Vind-X D30 L= 5374	2	31,3	62,6				0			ZLL	0,6	1,2
[x.63]			Vind-X D30 L= 6772	12	38,7	464,3				0			ZLL	0,7	8,6
[x.64]			Vind-X RHS100X100X6 L= 4910	1	84,5	84,5				0			ZLL	1,9	1,9
						74884,6									1205,7