

3 Fixing RUT.

- 1. Load trips using your preferred method.
- 2. Connect the XT to your PC and start tripmanager.
- 3. On the Trips preset your trips are shown.
- 4. Trips without a checkmark are 'Imported' and are subject to RUT behavior.
- 5. Trips with a checkmark are fixed.
- 6. Individual files can be (un)checked, and will be saved to the device.



7. Or select all files, use CTRL-A, and choose 'Functions/Set selected trips to saved'.



8. You can unplug your device.

9. On the trip planner your trips should be listed under 'Saved'



Notes:

- The first time you save a file, or better make a change on the device, you will notice a delay from 5-10 seconds. Next actions are fast.
- If you use the function 'Transfer to device' and check .trip files, the trips are fixed (set to saved) by default.