

## 3 Fixing RUT

- 1. Load trips using your preferred method.
- 2. Connect the XT(2) to your PC and start TripManager.
- 3. On the Trips preset your trips are shown.
- 4. Trips without a checkmark are 'Imported' and are subject to RUT behaviour.
- 5. Trips with a checkmark are fixed.
- 6. Individual files can be (un)checked, and will be saved to the device.



7. Or select all files, use CTRL-A, and choose 'Functions/Set selected trips to saved'.



8. You can unplug your device.

9. On the trip planner your trips should be listed under 'Saved'



## Notes:

- Trip Manager pre version V1.5 had an initial delay after the first write to the device. This has been fixed in V1.5.
- If you use the function 'Send to' and check .trip files, the trips are fixed (set to saved) by default.