

WORK PROCEDURE

PRO-MEC-001A

DISMANTLING A BOOM ON A CUBEX

GOAL

The purpose of this procedure is to define a safe way for dismantling a drill boom with appropriate lifting equipment. For any other situation where the method could be other than that provided for in this procedure, a risk analysis must be performed.

APPLICATION

This procedure applies to all employees of MACHINES ROGER INTERNATIONAL.

INTERPRETATION

Staff with authority for the interpretation of this document are the Maintenance Manager or the Operations Manager. Any request for modification, revision or update must be made to one of these persons.

RESPONSIBILITIES

The worker is responsible for using this procedure for every dismantling of a drill boom with lifting equipment. The necessary tools must be inspected before using them.

METHOD

The supervisor will designate a team leader who will take care of all operations. This team leader must be a supervisor or a mechanic and will have to meet with the lifting equipment operator to explain the procedure in detail. In addition, he will be the only one authorized to communicate with the lifting equipment operator during the operation.

PROCEDURE

1. Lifting equipment must have a capacity of 6,000 pounds or more;
2. Position the drill at level so that it is stable;
3. Position the drive shaft (gear box) five feet from the table
4. Lay the boom on its support in the center of the drill.

DÉMANTÈLEMENT D'UN MÂT DE FORAGE AVEC DE L'ÉQUIPEMENT DE LEVAGE

5. Make sure all joysticks are in the neutral position.

6. Apply the lockout procedure

7. Remove the hydraulic hoses and install the numbered caps.

8. In order to swing the lifting point, attach four slings of equal length certified 5,000 pounds to the four corners of the mast, at the appropriate places (rings). They must be connected to each other by the center with a big shackle 1 inch in diameter. Then we approach the lifting equipment to attach the shackle.

9. Remove the slings without slackening

10. Remove the bolts as follows:

- remove three bolts
- keep a tight bolt, so on until the last bolt. So there must remain three triangle bolts.

11. Recheck the tension on the slings

12. Remove the last three bolts.

13. Stand in a safe place at least 12 feet from the drill and be visible to the hoist operator at all times.

VERY IMPORTANT: NEVER TOLERATE ANYONE UNDER THE BOOM.

14. Remove the boom from the drill and place it on the ground on blocks of wood.

15. No person shall remove the shackle until the boom is properly seated on the block, then the shackle can be removed from the hoist.



Karl Béchard
Maintenance Manager



Christian St-Amour
Operations Manager