

WORK PROCEDURE

SS-DD-005A

DRILL SET-UP

OBJECTIVE

The purpose of this work procedure is to present the safe and standardized method for moving drills by type.

APPLICATION

This procedure is applicable for all the move of any diamond drill

INTERPRETATION

Staff with authority for the interpretation of this document is the Operations manager. Any request for modification, revision or update must be made to this person.

RESPONSABILITIES

The supervisor has the responsibility to make sure that procedure is respected

MANDATORY PPES

- Basic protective equipment on the site
- Good grip gloves

TOOLS REQUIRED

- 48 inches lever bar

POSITIONNING

- Always use your legs to avoid back injury
- Must always have good balance
- Must have a good grip on the floor
- Must always have space to move back
- Nobody is around and/or in the shooting line
- If the bar slip, be ready to
 - Let the bar go
 - Not hold back the bar
 - Move back quickly


DRILL SET-UP

PROCEDURE

- For drills with a winch at the rear, make sure the drill winch is out of between the skates by at least 12 inches.
- Putting the drill head at the opposite end to the side you want to move will make your job easier.



- Slide the lever bar under the winch on the opposing side to which you want to move the drill.
- Always point the longest side of the bar down to ensure good grip on the floor.




- Push the bar with **your knees and your arms**.
- If you have trouble lifting the bar it is slid too far under the winch.



DRILL SET-UP

- For drills with a lifting ring, insert the lifting bar inside the lift ring.
- Always point the longest side of the bar down to ensure good grip on the floor.



- Push the bar with your knees and your arms.
- If you have trouble lifting the bar it is because it is slid too far into the ring.




Stéphane Tremblay
Health and Safety superintendent