Pro PDF check pdf

Reporting period: 10/1/2026 - 10/9/2026

Report ID: #8

Type: custom

Generated: 10/9/2026, 12:02:08 PM

Sensors: 5 (2 gas-capable)

Period: 10/1/2026 - 10/9/2026

Readings: 965 | Gas events: 4

GAS SAFETY: 4 EVENT(S) REQUIRE REVIEW

Gas was detected during this period. Review the event log below and verify ventilation in the affected areas.

Contents

01	Executive Summary	3
02	Gas Safety	4
03	Sensors Overview	5
04	Temperature Analysis	6
05	Maintenance Overview	10
06	Appendix: Methodology	11
07	Conclusion & Recommendations	12

Key Performance Indicators

Total Sensors
5

Total Readings
965

Active Alerts
25

Avg Temp
24.82C

Gas Events
4

Overdue Tasks
0

Key Findings

- 965 temperature readings collected from 5 sensors (2 gas-capable) between 10/1/2026 - 10/9/2026.
- 4 gas detection event(s) recorded, most recently on 10/8/2026, 12:00:00 PM. Immediate review recommended.
- 25 alert(s) triggered in period (21 high-temp, 0 low-temp, 4 gas) (readings min 17.32C / max 39.33C).
- 0 maintenance task(s) overdue; 0 completed in period.

GAS SAFETY: 4 EVENT(S) REQUIRE REVIEW

Gas was detected during this period. Review the event log below and verify ventilation in the affected areas.

Gas-Capable Sensors

Sensor	Location	Readings	Gas Events	Last Event
Limbe Sensor	Limbe Market, Blantyre	193	2	10/8/2026, 4:00:00 AM
CBD Sensor	Victoria Ave, Blantyre CBD	193	2	10/8/2026, 12:00:00 PM

Gas Event Log

Date/Time	Sensor	Location	Status
10/1/2026, 9:00:00 PM	CBD Sensor	Victoria Ave, Blantyre CBD	GAS DETECTED
10/7/2026, 11:00:00 AM	Limbe Sensor	Limbe Market, Blantyre	GAS DETECTED
10/8/2026, 4:00:00 AM	Limbe Sensor	Limbe Market, Blantyre	GAS DETECTED
10/8/2026, 12:00:00 PM	CBD Sensor	Victoria Ave, Blantyre CBD	GAS DETECTED

Sensor Distribution

Sensor ID	Name	Type	Status	Location	Last Reading
BTY-001	Chichiri Sensor	Temp	Active	Chichiri, Blantyre	28.12C
BTY-002	Limbe Sensor	Temp+Gas	Active	Limbe Market, Blantyre	29C
BTY-003	Soche Sensor	Temp	Active	Soche Hill, Blantyre	27.9C
BTY-004	CBD Sensor	Temp+Gas	Active	Victoria Ave, Blantyre CBD	28.46C
BTY-005	Chileka Sensor	Temp	Active	Chileka Airport, Blantyre	26.76C

Temperature Statistics

Average	Minimum	Maximum	Total	Gas Events
24.82C	17.32C	39.33C	965	4

Detailed Readings

Date/Time	Sensor	Temperature	Gas	Location
10/1/2026, 2:00:00 AM	Chichiri Sensor	20.1C	N/A	Chichiri, Blantyre
10/1/2026, 2:00:00 AM	Limbe Sensor	20.2C	0	Limbe Market, Blantyre
10/1/2026, 2:00:00 AM	Soche Sensor	20.7C	N/A	Soche Hill, Blantyre
10/1/2026, 2:00:00 AM	CBD Sensor	19.1C	0	Victoria Ave, Blantyre CBD
10/1/2026, 2:00:00 AM	Chileka Sensor	19.4C	N/A	Chileka Airport, Blantyre
10/1/2026, 3:00:00 AM	Chichiri Sensor	17.6C	N/A	Chichiri, Blantyre
10/1/2026, 3:00:00 AM	Limbe Sensor	19.1C	0	Limbe Market, Blantyre
10/1/2026, 3:00:00 AM	Soche Sensor	19.2C	N/A	Soche Hill, Blantyre
10/1/2026, 3:00:00 AM	CBD Sensor	20.8C	0	Victoria Ave, Blantyre CBD
10/1/2026, 3:00:00 AM	Chileka Sensor	19.5C	N/A	Chileka Airport, Blantyre
10/1/2026, 4:00:00 AM	Chichiri Sensor	18.9C	N/A	Chichiri, Blantyre
10/1/2026, 4:00:00 AM	Limbe Sensor	18.4C	0	Limbe Market, Blantyre
10/1/2026, 4:00:00 AM	Soche Sensor	18.0C	N/A	Soche Hill, Blantyre
10/1/2026, 4:00:00 AM	CBD Sensor	20.4C	0	Victoria Ave, Blantyre CBD
10/1/2026, 4:00:00 AM	Chileka Sensor	20.1C	N/A	Chileka Airport, Blantyre
10/1/2026, 5:00:00 AM	Chichiri Sensor	20.1C	N/A	Chichiri, Blantyre
10/1/2026, 5:00:00 AM	Limbe Sensor	19.5C	0	Limbe Market, Blantyre
10/1/2026, 5:00:00 AM	Soche Sensor	20.5C	N/A	Soche Hill, Blantyre
10/1/2026, 5:00:00 AM	CBD Sensor	21.3C	0	Victoria Ave, Blantyre CBD

Temperature Analysis (Continued)

Date/Time	Sensor	Temperature	Gas	Location
10/1/2026, 5:00:00 AM	Chileka Sensor	20.7C	N/A	Chileka Airport, Blantyre
10/1/2026, 6:00:00 AM	Chichiri Sensor	20.9C	N/A	Chichiri, Blantyre
10/1/2026, 6:00:00 AM	Limbe Sensor	20.9C	0	Limbe Market, Blantyre
10/1/2026, 6:00:00 AM	Soche Sensor	21.2C	N/A	Soche Hill, Blantyre
10/1/2026, 6:00:00 AM	CBD Sensor	22.1C	0	Victoria Ave, Blantyre CBD
10/1/2026, 6:00:00 AM	Chileka Sensor	19.9C	N/A	Chileka Airport, Blantyre
10/1/2026, 7:00:00 AM	Chichiri Sensor	20.5C	N/A	Chichiri, Blantyre
10/1/2026, 7:00:00 AM	Limbe Sensor	38.3C	0	Limbe Market, Blantyre
10/1/2026, 7:00:00 AM	Soche Sensor	20.8C	N/A	Soche Hill, Blantyre
10/1/2026, 7:00:00 AM	CBD Sensor	21.5C	0	Victoria Ave, Blantyre CBD
10/1/2026, 7:00:00 AM	Chileka Sensor	21.2C	N/A	Chileka Airport, Blantyre
10/1/2026, 8:00:00 AM	Chichiri Sensor	37.0C	N/A	Chichiri, Blantyre
10/1/2026, 8:00:00 AM	Limbe Sensor	21.9C	0	Limbe Market, Blantyre
10/1/2026, 8:00:00 AM	Soche Sensor	23.2C	N/A	Soche Hill, Blantyre
10/1/2026, 8:00:00 AM	CBD Sensor	22.2C	0	Victoria Ave, Blantyre CBD
10/1/2026, 8:00:00 AM	Chileka Sensor	23.1C	N/A	Chileka Airport, Blantyre
10/1/2026, 9:00:00 AM	Chichiri Sensor	24.1C	N/A	Chichiri, Blantyre
10/1/2026, 9:00:00 AM	Limbe Sensor	25.2C	0	Limbe Market, Blantyre
10/1/2026, 9:00:00 AM	Soche Sensor	24.6C	N/A	Soche Hill, Blantyre
10/1/2026, 9:00:00 AM	CBD Sensor	25.1C	0	Victoria Ave, Blantyre CBD
10/1/2026, 9:00:00 AM	Chileka Sensor	23.2C	N/A	Chileka Airport, Blantyre
10/1/2026, 10:00:00 AM	Chichiri Sensor	24.1C	N/A	Chichiri, Blantyre
10/1/2026, 10:00:00 AM	Limbe Sensor	26.9C	0	Limbe Market, Blantyre
10/1/2026, 10:00:00 AM	Soche Sensor	27.1C	N/A	Soche Hill, Blantyre
10/1/2026, 10:00:00 AM	CBD Sensor	26.5C	0	Victoria Ave, Blantyre CBD
10/1/2026, 10:00:00 AM	Chileka Sensor	25.4C	N/A	Chileka Airport, Blantyre
10/1/2026, 11:00:00 AM	Chichiri Sensor	26.8C	N/A	Chichiri, Blantyre
10/1/2026, 11:00:00 AM	Limbe Sensor	28.3C	0	Limbe Market, Blantyre
10/1/2026, 11:00:00 AM	Soche Sensor	26.8C	N/A	Soche Hill, Blantyre
10/1/2026, 11:00:00 AM	CBD Sensor	28.3C	0	Victoria Ave, Blantyre CBD

Temperature Analysis (Continued)

Date/Time	Sensor	Temperature	Gas	Location
10/1/2026, 11:00:00 AM	Chileka Sensor	27.1C	N/A	Chileka Airport, Blantyre
10/1/2026, 12:00:00 PM	Chichiri Sensor	28.4C	N/A	Chichiri, Blantyre
10/1/2026, 12:00:00 PM	Limbe Sensor	28.5C	0	Limbe Market, Blantyre
10/1/2026, 12:00:00 PM	Soche Sensor	27.5C	N/A	Soche Hill, Blantyre
10/1/2026, 12:00:00 PM	CBD Sensor	28.5C	0	Victoria Ave, Blantyre CBD
10/1/2026, 12:00:00 PM	Chileka Sensor	29.2C	N/A	Chileka Airport, Blantyre
10/1/2026, 1:00:00 PM	Chichiri Sensor	29.5C	N/A	Chichiri, Blantyre
10/1/2026, 1:00:00 PM	Limbe Sensor	28.2C	0	Limbe Market, Blantyre
10/1/2026, 1:00:00 PM	Soche Sensor	29.1C	N/A	Soche Hill, Blantyre
10/1/2026, 1:00:00 PM	CBD Sensor	30.2C	0	Victoria Ave, Blantyre CBD
10/1/2026, 1:00:00 PM	Chileka Sensor	27.8C	N/A	Chileka Airport, Blantyre
10/1/2026, 2:00:00 PM	Chichiri Sensor	30.2C	N/A	Chichiri, Blantyre
10/1/2026, 2:00:00 PM	Limbe Sensor	29.9C	0	Limbe Market, Blantyre
10/1/2026, 2:00:00 PM	Soche Sensor	29.3C	N/A	Soche Hill, Blantyre
10/1/2026, 2:00:00 PM	CBD Sensor	28.9C	0	Victoria Ave, Blantyre CBD
10/1/2026, 2:00:00 PM	Chileka Sensor	28.3C	N/A	Chileka Airport, Blantyre
10/1/2026, 3:00:00 PM	Chichiri Sensor	29.9C	N/A	Chichiri, Blantyre
10/1/2026, 3:00:00 PM	Limbe Sensor	31.4C	0	Limbe Market, Blantyre
10/1/2026, 3:00:00 PM	Soche Sensor	29.0C	N/A	Soche Hill, Blantyre
10/1/2026, 3:00:00 PM	CBD Sensor	29.9C	0	Victoria Ave, Blantyre CBD
10/1/2026, 3:00:00 PM	Chileka Sensor	28.5C	N/A	Chileka Airport, Blantyre
10/1/2026, 4:00:00 PM	Chichiri Sensor	30.0C	N/A	Chichiri, Blantyre
10/1/2026, 4:00:00 PM	Limbe Sensor	31.1C	0	Limbe Market, Blantyre
10/1/2026, 4:00:00 PM	Soche Sensor	30.9C	N/A	Soche Hill, Blantyre
10/1/2026, 4:00:00 PM	CBD Sensor	31.4C	0	Victoria Ave, Blantyre CBD
10/1/2026, 4:00:00 PM	Chileka Sensor	28.9C	N/A	Chileka Airport, Blantyre
10/1/2026, 5:00:00 PM	Chichiri Sensor	30.0C	N/A	Chichiri, Blantyre
10/1/2026, 5:00:00 PM	Limbe Sensor	29.4C	0	Limbe Market, Blantyre
10/1/2026, 5:00:00 PM	Soche Sensor	29.8C	N/A	Soche Hill, Blantyre
10/1/2026, 5:00:00 PM	CBD Sensor	30.7C	0	Victoria Ave, Blantyre CBD

Temperature Analysis (Continued)

Date/Time	Sensor	Temperature	Gas	Location
10/1/2026, 5:00:00 PM	Chileka Sensor	28.9C	N/A	Chileka Airport, Blantyre
10/1/2026, 6:00:00 PM	Chichiri Sensor	26.8C	N/A	Chichiri, Blantyre
10/1/2026, 6:00:00 PM	Limbe Sensor	28.6C	0	Limbe Market, Blantyre
10/1/2026, 6:00:00 PM	Soche Sensor	28.4C	N/A	Soche Hill, Blantyre
10/1/2026, 6:00:00 PM	CBD Sensor	29.9C	0	Victoria Ave, Blantyre CBD
10/1/2026, 6:00:00 PM	Chileka Sensor	28.0C	N/A	Chileka Airport, Blantyre
10/1/2026, 7:00:00 PM	Chichiri Sensor	26.1C	N/A	Chichiri, Blantyre
10/1/2026, 7:00:00 PM	Limbe Sensor	28.2C	0	Limbe Market, Blantyre
10/1/2026, 7:00:00 PM	Soche Sensor	27.8C	N/A	Soche Hill, Blantyre
10/1/2026, 7:00:00 PM	CBD Sensor	27.2C	0	Victoria Ave, Blantyre CBD
10/1/2026, 7:00:00 PM	Chileka Sensor	27.0C	N/A	Chileka Airport, Blantyre
10/1/2026, 8:00:00 PM	Chichiri Sensor	26.5C	N/A	Chichiri, Blantyre
10/1/2026, 8:00:00 PM	Limbe Sensor	27.2C	0	Limbe Market, Blantyre
10/1/2026, 8:00:00 PM	Soche Sensor	25.4C	N/A	Soche Hill, Blantyre
10/1/2026, 8:00:00 PM	CBD Sensor	26.7C	0	Victoria Ave, Blantyre CBD
10/1/2026, 8:00:00 PM	Chileka Sensor	24.6C	N/A	Chileka Airport, Blantyre
10/1/2026, 9:00:00 PM	Chichiri Sensor	25.0C	N/A	Chichiri, Blantyre
10/1/2026, 9:00:00 PM	Limbe Sensor	23.6C	0	Limbe Market, Blantyre
10/1/2026, 9:00:00 PM	Soche Sensor	23.4C	N/A	Soche Hill, Blantyre
10/1/2026, 9:00:00 PM	CBD Sensor	23.9C	GAS	Victoria Ave, Blantyre CBD
10/1/2026, 9:00:00 PM	Chileka Sensor	24.3C	N/A	Chileka Airport, Blantyre

* Showing first 100 of 965 readings

Maintenance Summary

Total Tasks	Completed	Overdue	Due Soon
0	0	0	0

How This Report Was Produced

- Readings are collected hourly from registered sensors; each record carries temperature, GPS position and, for gas-capable sensors, a binary gas flag (1 = gas detected, 0 = clear).
- Sensors without gas hardware store no gas value (shown as N/A) so a 0 reading is never confused with missing hardware.
- Temperature alerts trigger when a reading exceeds the sensor's configured min/max thresholds; every gas detection raises a GAS alert.
- Reporting period: 10/1/2026 - 10/9/2026. Figures on the cover and in the Executive Summary reflect this window.
- Detailed tables show the first 100 readings and first 50 gas events; complete data is available in the JSON/CSV exports.

Conclusion & Recommendations

Based on the data collected during the report period, the following observations and recommendations are made:

- **Regular monitoring of sensor calibration is recommended**
- **Schedule preventive maintenance for sensors showing irregular patterns**
- **Review temperature thresholds for sensors with frequent alerts**
- **Consider adding additional sensors in critical monitoring areas**
- **Investigate 4 gas detection event(s) immediately and verify ventilation in affected areas**

This report was automatically generated by TempGuard.
For questions or support, please contact your system administrator.