

Temperature Analysis

Temperature Monitoring System Report

Average	Minimum	Maximum	Total
21.26C	1.20C	41.00C	20

Detailed Readings

Date/Time	Sensor	Temperature	Location
6/4/2026, 2:12:10 PM	Computer Lab Sensor	2.5C	Computer Lab Building
6/4/2026, 2:12:10 PM	Server Room Sensor	1.2C	Building A
6/4/2026, 3:12:10 PM	Computer Lab Sensor	6.1C	Computer Lab Building
6/4/2026, 3:12:10 PM	Server Room Sensor	5.4C	Building A
6/4/2026, 4:12:10 PM	Computer Lab Sensor	9.4C	Computer Lab Building
6/4/2026, 4:12:10 PM	Server Room Sensor	8.9C	Building A
6/4/2026, 5:12:10 PM	Computer Lab Sensor	12.8C	Computer Lab Building
6/4/2026, 5:12:10 PM	Server Room Sensor	14.3C	Building A
6/4/2026, 6:12:10 PM	Computer Lab Sensor	16.9C	Computer Lab Building
6/4/2026, 6:12:10 PM	Server Room Sensor	19.7C	Building A
6/4/2026, 7:12:10 PM	Computer Lab Sensor	21.5C	Computer Lab Building
6/4/2026, 7:12:10 PM	Server Room Sensor	24.5C	Building A
6/4/2026, 8:12:10 PM	Computer Lab Sensor	27.3C	Computer Lab Building
6/4/2026, 8:12:10 PM	Server Room Sensor	31.2C	Building A
6/4/2026, 9:12:10 PM	Computer Lab Sensor	36.8C	Computer Lab Building
6/4/2026, 9:12:10 PM	Server Room Sensor	39.5C	Building A
6/4/2026, 10:12:10 PM	Computer Lab Sensor	32.4C	Computer Lab Building
6/4/2026, 10:12:10 PM	Server Room Sensor	35.6C	Building A

Temperature Analysis (Continued)

Temperature Monitoring System Report

Date/Time	Sensor	Temperature	Location
6/4/2026, 11:12:10 PM	Computer Lab Sensor	38.2C	Computer Lab Building
6/4/2026, 11:12:10 PM	Server Room Sensor	41.0C	Building A

Maintenance Overview

Temperature Monitoring System Report

Total Tasks	Completed	Overdue	Due Soon
2	0	1	0

undefined Tasks by Type

Task Type	Count
Calibration	1
Hardware Repair	1

Maintenance Tasks Details

Temperature Monitoring System Report

Title	Type	Due Date	Status	Priority
Calibration check	Calibration	7/4/2026	OK	Medium
Fix Power Supply	Hardware Repair	6/4/2026	Overdue	High

Report Summary

Temperature Monitoring System Report

Based on the data collected during the report period, the following observations and recommendations are made:

- Regular monitoring of sensor calibration is recommended
- Schedule preventive maintenance for sensors showing irregular patterns
- Review temperature thresholds for sensors with frequent alerts
- Consider adding additional sensors in critical monitoring areas