Safety. Reliability. Quality.
TECHNICAL SERVICES
UNIVERSAL ORLANDO

Certification Process

Darkmoor PQS

All Modules Completed

Step 1. Technician has read, reviewed, and understands all PQS Modules for the listed venue above
Step 2. Technician demonstrates competency in each area of the PQS Modules to the Qualified Technician
Step 3. Required parties have signed all tasks on the attached PQS Venue Signature Sheet(s)
Step 4. Technician has read and signed all documents in the listed venue ECN/DCN/MB/TD on Success Factors
Step 5. Technician successfully passes a board certification review conducted by the listed venue Management
Step 6. Technician is certified to perform preventive maintenance by meeting Personal Qualification Standards (PQS) at the listed venue by the UO Ride & Show PQS Approval Group Member.

RCM Technical Trainer will verify the Technician has completed step 4 and read and signed all ECN/DCN/ MB/ TDs on Success Factors & Maximo for the venue listed above.

Frederick Herrera / 703153842

(Print) RCM Technical Trainer Name/Team Member ID | *RCM Technical Trainer Signature* | *Sign/Date/Time*

RCM Technical Trainer has verified that the technician below has completed steps 1-3 and all PQS sign offs on the attached venue signature sheet(s). The RCM Technical Trainer recommends the technician for board certification review by the listed venue management team.

Frederick Herrera / 703153842

(Print) RCM Technical Trainer Name/Team Member ID | RCM Technical Trainer Signature | Sign/Date

"Technician understands that the PMs included on PQS Venue Signature Sheet(s) are not necessarily inclusive of all work they will be assigned at their venue. It is the Technician's responsibility to read all Job Plans on assigned Work Orders."

Tyler Thomas / 703109058

(Print) Technician Name/Team Member ID | Technician Signature | Sign/Date

Tyler Thomas / 703109058

(Print) Technician Name/Team Member ID

has successfully passed the board certification review for

Darkmoor

(Print) Venue Name

by the Technical Services Management team listed below

(Print) Supervisor Name/ID | Supervisor Signature | Sign/Date

(Print) Manager Name/ID | Manager Signature | Sign/Date

This technician has met the Personal Qualifications Standards of the venue listed above and permitted to perform preventive maintenance procedures.

(Print) UO Ride & Show PQS Approval Group Member | UO Ride & Show PQS Approver Signature | Sign/Date

WO:# WR10955970

*(Initials) Reviewed by PQS Manager*_____