Safety. Reliability. Quality.
TECHNICAL SERVICES
UNIVERSAL ORLANDO

Certification Process for

Monsters Unchained/UC_L1M4 -PQS

Step 1. Technician has read, reviewed, and understands all PQS Modules for the listed venue above
Step 2. Technician demonstrates competency in each area of the module to the Qualified Technician then signs off in the appropriate section below.
Step 3. All required parties have signed on the attached PQS Certification Single Module Sign Off Sheet.
Step 4. RCM Technical Trainer, Venue Supervisor and Venue Manager conduct a final compliance review.
Step 5. Technician is certified to perform preventive maintenance associated with the listed module on this document by the UO Ride & Show PQS Approval Group Member.

Single Module Certification Tasks	*RCM Technical Trainer Signature*	*Date / Time*
All LOTO sign offs have been completed for the module listed above		
Module(s) listed on this sheet have been completed and reviewed		
All Preventive Maintenance sign offs have been completed for the module listed above		
Technician has performed successfully to a PQS Certified Technician		
All (ECNs, DCNs, MB and SOPs) on Success Factors have been completed		

The technician below has completed the sections of PQS Module Certifications listed above and is recommended for board certification review conducted by the venue management staff below.

Frederick Herrera / 703153842

(Print) RCM Technical Trainer Name/Team Member ID

RCM Technical Trainer Signature Sign/Date

"Technician understands that the PMs included on PQS Venue Signature Sheet(s) are not necessarily inclusive of all work they will be assigned at their venue. It is the Technician's responsibility to read all Job Plans on assigned Work Orders."

Eric Knutson / 206827854

(Print) Technician Name/Team Member ID

Technician Signature Sign/Date

Eric Knutson / 206827854

(Print) Technician Name/Team Member ID

has successfully passed the board certification review for

Monsters Unchained/UC_L1M4

(Print) Venue Name/Module # ie FJ_L1M1v2

by the Technical Services Management team listed below.

(Print) Supervisor Name/ID

Supervisor Signature Sign/Date

(Print) Manager Name/ID

Manager Signature Sign/Date

This technician has met the Personal Qualifications Standards of the venue listed above and permitted to perform preventive maintenance procedure.

(Print) UO Ride & Show PQS Approval Group Member

UO Ride & Show PQS Approver Signature Sign/Date

WO:# 13902470

*(Initials) Reviewed by PQS Manager*_____