


SmartMeterSide

File: SmartMeterSide.kicad_sch

ExtensionSide

File: ExtensionSlide.kicad_sch


Sheet: /		
File: P1SmartMeter.kicad_sch		
Title:		
Size: A4	Date:	Rev:
KiCad E.D.A. 8.0.5		Id: 1/3



4 and 5 twisted
7 and 8 twisted

Sheet: /SmartMeterSide/		
File: SmartMeterSide.kicad_sch		
Title:		
Size: A3	Date:	Rev:
KiCad E.D.A. 8.0.5		Id: 2/3

4 and 5 twisted
7 and 8 twisted



6N137
 $I_F = 5\text{mA}$
 $V_F = 1.15\text{V} \Rightarrow 1.42\text{V}$
 $I_F = 10\text{mA}$
 $V_F = 1.2\text{V} \Rightarrow 1.45\text{V}$
 $(5 - 0.5 - 1.45)/330 = 9\text{mA}$

Add (red) LED (1mA max) to indicate 5V connected