



A310

Checklist by ElectroxSoldier Published November 2022 Version 1.0

PRELIMINARY PREPARATION

BATTERIES	
CHECK ELEC PUMPS SWITCH OFF	CHECK
DO NOT PRESSURISE GREEN HYDRAULIC	SYSTEM
WITHOUT GROUND CLEARANCE	OTOTEW
WIPER SWITCHES	OFF
GEAR LEVER	
SLATS-FLAPS HANDLE IN AGRE	
REVERSER LEVERS	
FUEL LEVERS	
WEATHER RADAR	
EXTERNAL POWER (IF AVAIL) ESTA	
APU FIRE SYSTEM	
PRESS SQUIB TEST, PRESS LOOP TEST	
APU AS REC	QUIRED
APU START FLOW:	
INNER TK PUMP 2 SWITCH	ON
APU MASTER	
APU START	
IRS MODE SELECTORS	
ISDU	SET
DYSP SEL TO PPOS, SYS DYSPL TO 1	011
OXYGEN LO PR SUPPLY SWITCHES	_
ANN LIGHT	
VHF RADIOS AS REC	JUIKED

FLIGHT DECK PREPARATION

FMC	
EFB	SETUP
NO SMOKING	AUTO
SEAT BELTS	ON
HYD PWR PANEL	SET / CHECK
FLT RCDR GND CTL	ON
STROBE LIGHTS	AUTO
NAV & LOGO LIGHTS	ON
ATS LEVER	ON
PITCH TRIM & YAW DAMPER LVRS	ON
IRS MUST BE ALIGNED	
IRS ALIGN MODE LIGHTS MUST BE EXTIN	IGUISHED
ELEC PWR PANEL	CHECK
ENG 1 FIRE PANELC	HECK / TEST
PRESS SQUIB TEST, PRESS LOOP TEST	

ELEC IND PANEL	CHECK
ENG PANEL	
FUEL PANEL	SET
WHEN FUELLING COMPLETE, ALL TK F	PUMPS ON
CABIN PRESS PANEL	CHECK
WINDOW HEATER SWITCHES	ON
PROBE HEAT SWITCHES	
ENG 2 FIRE PANEL	. CHECK / TEST
PRESS SQUIB TEST, PRESS LOOP TES	T
VENT PANEL	CHECK
FAMED EVIT LIGHT	OI ILOIN
EMER EXIT LIGHT	
AIR BLEED PANEL	CHECK
APU BLEEDC	N (IF APU AVAIL)
COND TEMP PANEL	SET / CHECK
ECON FLOW	
ECON FLOW	OIN
PACK TEMP PANEL	
OXYGEN PANEL	CHECK
EFIS CONTROL PANEL	CHECK
FCP	
FOF	OI IEON
CAPT SW PANEL	
STANDBY AIRSPEED INDICATOR	CHECK
RMI, PFD, ND	CHECK
ALTIMETER	
IVSI	
ADF RMI	CHECK
EGPWS BUTTON	
CLOCK	
OTANDOV LIGORIZON	SET / CITEON
STANDBY HORIZON	
STANDBY ALTIMETER	CHECK
SLAT-FLAP POSITION INDICATOR	(SFPI) CHECK
BRAKES PRESSURE GAUGE	` '
ALTERNATE BRAKING SYSTEM	
PARKING BRAKE	
AUTO BRK SWITCHES	EXTINGUISHED
REV & REV UNLK LIGHTS	
ENGINE INSTRUMENTS & LIGHTS	
LANDING ELEVATION	
LDG GEAR WARN	TEST
BRK FAN	AS REQUIRED
SPEED BRAKE HANDLE	
TAKEOFF WARNING	CHECK
FUEL LEVERS	OFF
ATC TRANSPONDER / TCAS	SFT
ADFS	
RUD TRIM	
WEATHER RADAR	TEST
FMS ROUTE	
PERFORMANCE DATA	
PERFURIVIAINUE DATA	CALCULATE
EFB → PERFORMANCE CALCULATOR	
TRP	SET



A310

Checklist by ElectroxSoldier Published November 2022 Version 1.0

BEFORE START

COCKPIT PREP SIGNS FUEL QUANTITY NAVIGATION (FMS, RADIOS) LDG ELEVATION ALTIMETERS TAKEOFF WARNING BRAKES / ANTI-SKID REQUEST PUSHBACK AND ST	ON / AUTOKG/LB, CHECKED CHECKED, SETSET SET, FTCHECKEDON
WINDOWS / DOORS BEACON PARKING BRAKE	OŃ

ENGINE START

AREA CLEAR TO STARTIGNITION SELECTOR	
SELECT A IF CAPTAIN PF, B IF FO PF	
ENGINE 1 / 2 START SWITCH	PRESS
AT 20% N2	FUEL LEVER ON
REPEAT PREVIOUS TWO STEPS FOR	OTHER ENGINE

AFTER START

IGNITION	AS REQUIRED
APU BLEED	AS REQUIRED
APU MASTER	AS REQUIRED
ANTI ICE	AS REQUIRED
SPEEDBRAKE	ARM
RUDDER TRIM	RESET, CHECK 0
SLATS-FLAPS	SET FOR TAKEOFF
TRIM	SET FOR TAKEOFF

TAXI

OBTAIN
TAXI
RELEASE
CHECK
MAX
SET
TEST

BEFORE TAKEOFF

FLIGHT CONTROLS	
CABIN TCAS WEATHER RADAR PACKS IGNITION ANTI-ICE	TA/RAONAS RQRDAS RQRD

TAKEOFF

CLOCK	START
THROTTLES	ADVANCE
BRAKES	RELEASE
GO-LEVERS	TRIGGER
BOTTOM LEFT SCREW ON FCU TO TRI	GGER GO-LEVERS

AFTER TAKEOFF / CLIMB

SLATS / FLAPSLDG GEAR	
PACKS	
SPEEDBRAKE	
EXTERIOR LIGHTS:	
NOSE LIGHT	OFF
RWY TURN OFF	OFF
ANTI-ICE	AS REQUIRED
IGNITION	AS REQUIRED
APU	OFF
PASSING TRANSITION ALTITU	JDE
ALTIMETERS	SET (BOTH)

LANDING LIGHTS RETRACT / OFF SEAT BELTS AS REQUIRED BELOW 10000FT MAX 250 KIAS





A310

Checklist by ElectroxSoldier Published November 2022 Version 1.0

DESC	ENT
ANTI-ICE	AS REQUIRED
PASSING TRANSITION AL ALTIMETERSBELOW 10000FT	
SEAT BELTSRWY TURN OFFLANDING LIGHTS	ON
MAX SPEED	

APPROACH	
SLATS	REDUCE
ONCE CLEARED FOR APPROACH:	
FCU LAND PB	PRESS
LOC CAPTURE	MONITOR
G/S CAPTURE	
AT 2000FT AGL, OR ONE DOT BELO	W G/S:
FLAPS	SELECT 15/15
SPEED	REDUCE
TARGET 160-180KTS OR "F" SPEED UNLESS	INSTRUCTED
OTHERWISE BY ATC	
SPEED BRAKES CHEC	K RETRACTED

LANDING LANDING GEAR DOWN GROUND SPOILERS ARM NOSE LIGHT T.O. FLAPS SELECT 15/20 ONCE LANDING GEAR 3 GREENS FLAPS SELECT 30/40 ONCE FLAPS 20 AUTOBRAKE AS RQRD ANTI SKID CHECKED

AFTER LANDING
EXTERIOR LIGHTS: NOSE LIGHT
IGNITION

PARKING	
NOSE LIGHTO	FF
BEFORE TURNING TOWRADS PARKING STAND	
PARKING BRAKE(NC
APU BLEED	NC
ENGINE FUEL LEVERS O	FF
ELAPSED TIMESTO	ЭP
BEACON O	FF
CABIN PRESSURECHEC	CK
SEAT BELT SIGNS O	FF
PARKING BRAKE AS REQUIRI	ED
FUEL PUMPSO	FF
WINDOW HEATER SWITCHES O	FF
PROBE HEATO	FF
IRS CHECK / AS REQUIRI	
BRAKE FANS AS REQUIR	



A310

Checklist by ElectroxSoldier Published November 2022 Version 1.0

SECURING AIRCRAFT

IRS	OFF OFF LL OFF OFF QUIRED
APUEMERGENCY EXIT LIGHTS	DISARM

GO AROUND

GO LEVER	TRIGGER
BOTTOM LEFT SCREW ON FCU TO A	CTIVATE GO-LEVERS
THROTTLE LEVERS ADVAN	CE TO G.A. THRUST
ROTATION	PERFORM
FLAPSI	RETRACT ONE STEP
POSITIVE CLIMB	GEAR UP
NAV OR HDG MODE	SELECT
AT ACCELERATION ALTITUDE	:
LVL/CH	SELECT

REJECTED TAKEOFF

ANNOUNCE	"STOP"
THRUST LEVERS	
A/THR	
REVERSE THRUST	
PARKING BRAKE	APPLY
ECAM ACTIONS	COMPLETE
EVACUATION AS REQUIRED.	INITIATE

EMERGENCY DESCENT

CREW OXY MASKS	ON
HEADING	TURN AND HDG SEL
ALTITUDE	TURN AND LVL/CH
SPD/MACH	SELECT SPEED
THROTTLES	IDLE
SPD BRK	FULL
SPEED	ADJUST AS REQUIRED

OF AT DELTO	ON
SEAT BELTS	
NO SMOKING	ON
IGNITION	CONT. RELIGHT
ATC	NOTIFY
TRANSPONDER	7700
FCU ALT	MEA/MORA
LDG ALT	SET
OXYGEN PASSENGER	MAN OVRD
(CAB ALT ABOVE 14000FT)	
L/G LEVER DOWN	CONSIDER
L/G MAY BE LOWERED WHEN BELC	W 20000FT AND
BELOW 270 KIAS TO INCREASE DES	SCENT

SEVERE TURBULENCE

CEAT DELTC	ON
SEAT BELTS	ON
NO SMOKING SIGN	ON
IGNITION	CONT RELIGHT
AP	KEEP IN CMD
SPEED / MACH SETTING KNO	OB PULL/ADJUST
A / THR	KEEP ENGAGED
TARGET SPEED AND THRUS	T READ AND NOTE
SPD / MACH	. SET TARGET SPEED
ALTITUDE	CONSIDER DESCENT
TRIM TANK MODE	FWD

AIRFRAME LIMITS

MAX TAKEOFF WEIGHT 153000 KG / 337307 LBS
MAX LANDING WEIGHT 124000 KG / 273373 LBS
MAX ZERO FUEL WEIGHT 114000 KG / 251326 LBS
OPERATING EMPTY WEIGHT 80000 KG / 176370 LBS

PAYLOAD LIMITS

MAX FUEL QUANTITY 60300 KG / 132940 LBS
MAX TOTAL PAYLOAD WEIGHT 35440 KG / 78131 LBS
MAX PASSENGER WEIGHT 19040 KG / 41976 LBS
MAX CARGO HOLD WEIGHT 16400 KG / 36155 LBS