Turkey Creek

wa-1028-002

Severity Score 4.5

Common:

5mi NE of Mossy Head

Shoal River Drainage: Land owner: Unknown

GPS: 30.824039425, -86.255678894

<u>County</u>: <u>PLSS(T-R-S)</u>: Parcel No.:

Walton 4N-20W-28 Unknown

State:







Risk Factor	Ranking	Score
Channel Stability	Fair	1
Channel Alteration	None	0
Bank Erosion	Active	1
BEHI	High	1
Local NPSP	No Evidence	0
Shoring Structures	Not Present	0
Pipe Discharge	Not Present	0
Water Odors	Not Present	0
Fish Passage Barrier	Not Present	0
RB: Riparian Buffer	0-29 ft	0.75
LB: Riparian Buffer	100+ ft	0
RB: Floodplain Access	None	0.75
LB: Floodplain Access	Full	0
	River Threat Index:	4.5

Within Range	Descriptive Field	
303(d) Yes	COLIFORMS, TURBIDITY	
No	N/A	
No	N/A	
Yes	VACANT RESIDENTIAL/ STREAMS AND WATERWAYS	
No	N/A	
No	N/A	
	Range Yes No No Yes No	

Additional Site Features Stream Channel Woody Material: Moderate Impoundments: Substrate Composition: Bank Material:

None Clay Marl Sand and Clay

Notes: Joyce Cordell is noted as a possible land owner. Logging road 0.3mi west of site? 60ft site reach.