Unnamed tributary

wa-0626-r-005

Sedimentation Risk Index

34

Common: 6.6mi SE of Florala

Drainage:Long CreekGPS:30.911070, -86.306770Land owner:Ricky & Jacqueline Adams- US, Joe & Cheryl Gillam-DS

East, Thomas & Doris Bell- DS West

County: Walton

 PLSS(T-R-S):
 5N-21-23/26

 Parcel No.:
 4.001; 1.001; 1

 Road Name:
 Campground Rd

State: Florida





Crossing Structure: DS

DS

| Risk Factor | Ranking | Score |
|---------------------------------|----------------------------|-------|
| US Channel Morph | PONDED | 1 |
| DS Channel Morph | Е | 5 |
| DS Bank Alteration | HIGH | 1 |
| Upstream Skew Angle | <5° | 5 |
| Crossing fill condition | Poor/Bare soil | 1 |
| Inlet/Outlet Condition | No Impairment | 5 |
| Road Approach Material | All Sand/Clay | 3 |
| Potential Eroded Volume Mean | <21 y ³ | 5 |
| Approach Slope Mean | >4% | 1 |
| Soil K Factor | < 0.20 | 5 |
| Upstream Rt Outlet | Bare soil | 0 |
| Upstream Lt Outlet | Bare soil | 0 |
| Upstream Rt Ditch | Bare soil | 0 |
| Upstream Lt Ditch | Bare soil | 0 |
| Downstream Rt Outlet | Bare soil | 0 |
| Downstream Lt Outlet | Bare soil | 0 |
| Downstream Rt Ditch | Bare soil | 0 |
| Downstream Lt Ditch | Bare soil | 0 |
| Outlet Total | Unimproved Outlet System | 1 |
| Ditches Total | Unimproved Drainage System | 1 |
| SRI Total | High Risk | 34 |



Additional Site Features

<u>Crossing Type and Quantity</u>: Culvert, 2 <u>Crossing Materials</u>: Metal

<u>Soil Types</u>: 13,15,22,40,31,32,60,69

Rt Approach Prism Fill: 0.35in Lt Approach Prism Fill: 0.25in

| Feature | Within Range | Descriptive Field | |
|-----------------------|-----------------|--|--|
| 303(d) | No | N/A | |
| Wetland Species | No | N/A | |
| Rare and Imperiled | No | N/A | |
| Land Use/ Cover | Yes | AGRICULTURAL/ UPLAND CONIFEROUS FORESTS | |
| Candidate Mussels | No | N/A | |
| Sturgeon C.H. | No | N/A | |

Notes: Second culvert 50 ft west of first, blocked