## Unnamed tributary

## ok-0429-r-014

Sedimentation Risk Index

Florida

State:

5.1mi SW of Laurel Hill Common:

Murder Creek <u>Drainage</u>: Dean & Deborah Clary Land owner:

GPS: 30.910200, -86.517086

County: Okaloosa  $\overline{PLSS(T-R-S)}$ : 5N-23-23

5.001 Parcel No.:

Road Name: W Plympton Road





Crossing Structure: DS



Risk Factor	Ranking	Score
US Channel Morph	PONDED	1
DS Channel Morph	PONDED	1
DS Bank Alteration	HIGH	1
Upstream Skew Angle	>30°	1
Crossing fill condition	Poor/Bare soil	1
Inlet/Outlet Condition	Blocked	1
Road Approach Material	All Sand/Clay	3
Potential Eroded Volume Mean	>40 y <sup>3</sup>	1
Approach Slope Mean	2.1-4%	3
Soil K Factor	< 0.20	5
Upstream Rt Outlet	Vegetated	1
Upstream Lt Outlet	Vegetated	1
Upstream Rt Ditch	Bare soil	0
Upstream Lt Ditch	Bare soil	0
Downstream Rt Outlet	Bare soil	0
Downstream Lt Outlet	Bare soil	0
Downstream Rt Ditch	Bare soil	0
Downstream Lt Ditch	Bare soil	0
Outlet Total	Partially Improved Outlet System	3
Ditches Total	Unimproved Drainage System	1
SRI Total	High Risk	22

1	
	Okaleosa Walton
<b>,产品最大的</b>	
The second secon	Google

**Descriptive Field** 

DISSOLVED OXYGEN, COLIFORMS

N/A

BLACKTIP SHINER, IRONCOLOR SHINER

Crossing Type and Quantity:	Culvert, 1
Crossing Materials:	Metal
Soil Types:	3,23,25,34
Rt Approach Prism Fill:	1.0in
Lt Approach Prism Fill:	1.0in

**Additional Site Features** 

Metal 3,23,25,34,36,37,39,40,43 1.0 in1.0in

Cover	Yes	N/A / WETLAND FORESTED MIX
Candidate Mussels	No	N/A
Sturgeon	No	N/A

Within

Range

Yes

No

Yes

Feature

303(d)

Wetland

Species Rare and

Imperiled

Notes: None