Unnamed tributary

co-0812-r-013b

Sedimentation Risk Index

Alabama

38

State:

7.0mi N of Florala Common:

GPS: 31.106053, -86.325597 Beaver Creek <u>Drainage</u>:

Land owner: Rayonier Forest Resources LP Covington 2N-17E-26

 \overline{PLSS} (T-R-S): Parcel No.:

Road Name: Tram Rd





Crossing Structure: DS

Ranking	Score
WETLAND	5
WETLAND	5
NATURAL	5
5-30°	3
Poor/Bare soil	1
Sed Islands/Scouring	3
All Sand/Clay	3
>40 y ³	1
<2%	5
< 0.20	5
Bare soil	0
Unimproved Outlet System	1
Unimproved Drainage System	1
	WETLAND WETLAND NATURAL 5-30° Poor/Bare soil Sed Islands/Scouring All Sand/Clay >40 y³ <22% <0.20 Bare soil Unimproved Outlet System

		Civington
		(Malong)
The second secon	A THE SAME OF THE STREET OF TH	Google

Feature	Within Range	Descriptive Field
303(d)	No	N/A
Wetland Species	No	N/A
Rare and Imperiled	No	N/A
Land Use/ Cover	Yes	N/A/ EVERGREEN PLANTATIONS
Candidate Mussels	No	N/A
Sturgeon C.H.	No	N/A

SRI Total **Additional Site Features**

Crossing Type and Quantity: Culvert, 1 PVC **Crossing Materials**:

Soil Types: Rt Approach Prism Fill: BoB,DmB,FoA,FuB,MBA,OrB,RaA

Medium Risk

0.25in Lt Approach Prism Fill: 0.5in

Notes: Culvert undersized for wetland drainage

38