## Horsehead Creek

## ok-0528-r-004

Sedimentation Risk Index

44

Florida

State:

2.9mi SE of Laurel Hill Common:

Pond Creek <u>Drainage</u>: Land owner: Robert Babcock GPS: 30.927819, -86.436811

Okaloosa  $\overline{PLSS(T-R-S)}$ : 5N-22-15

Parcel No.:

Road Name: Millside Rd



Crossing	Structure:	DS
----------	------------	----

Risk Factor	Ranking	Score
US Channel Morph	С	5
DS Channel Morph	С	5
DS Bank Alteration	MINOR/PARTIAL	3
Upstream Skew Angle	<5°	5
Crossing fill condition	Fair/Rip Rap	3
Inlet/Outlet Condition	No Impairment	5
Road Approach Material	All Sand/Clay	3
Potential Eroded Volume Mean	>40 y <sup>3</sup>	1
Approach Slope Mean	<2%	5
Soil K Factor	< 0.20	5
Upstream Rt Outlet	Concrete	0
Upstream Lt Outlet	Rip Rap	1
Upstream Rt Ditch	Concrete	0
Upstream Lt Ditch	Bare soil	0
Downstream Rt Outlet	Rip Rap	1
Downstream Lt Outlet	Bare soil	0
Downstream Rt Ditch	Bare soil	0
Downstream Lt Ditch	Bare soil	0
Outlet Total	Partially Improved Outlet System	3
Ditches Total	Unimproved Drainage System	1
SRI Total	Medium Risk	44

**Additional Site Features** 

Crossing Type and Quantity: Bridge, 1 Crossing Materials: Wood

4,13,16,23,36,40,41,45,44,45,46,49,50 Soil Types:

Rt Approach Prism Fill: Lt Approach Prism Fill: 1.0in

	Escambia Covington
	是是是
<b>第二上上了会计算等度</b>	Okaloosa Walton
A Supply States	100
	Google
	The state of

Feature	Within Range	Descriptive Field
303(d)	No	N/A
Wetland Species	No	N/A
Rare and Imperiled	No	N/A
Land Use/ Cover	Yes	AGRICULTURAL/ WETLAND FORESTED MIX
Candidate Mussels	No	N/A
Sturgeon C.H.	No	N/A

Notes: Appears to be sediment loading from US? Source unknown