## Yellow River

## co-0609-004

Severity Score

1.5

Alabama

<u>State</u>:

Common:11.8mi NW of FloralaDrainage:Blackwater BayGPS: 31.0501274, -86.519192Land owner:LB: Nathaniel Wright, Tr. / RB: USA

Covington 1N-15E-14 <u>County</u>: <u>PLSS</u>:

Parcel No.: 3/1





| Risk Factor           | Ranking             | Score |
|-----------------------|---------------------|-------|
| Channel Stability     | Good                | 0.5   |
| Channel Alteration    | None                | 0     |
| Bank Erosion          | Historic            | 0.5   |
| BEHI                  | Moderate            | 0.5   |
| Local NPSP            | No Evidence         | 0     |
| Shoring Structures    | Not Present         | 0     |
| Pipe Discharge        | Not Present         | 0     |
| Water Odors           | Not Present         | 0     |
| Fish Passage Barrier  | Not Present         | 0     |
| RB: Riparian Buffer   | 100+ ft             | 0     |
| LB: Riparian Buffer   | 100+ ft             | 0     |
| RB: Floodplain Access | Full                | 0     |
| LB: Floodplain Access | Full                | 0     |
|                       | River Threat Index: | 1.5   |

| Feature   | Within<br>Range | Descriptive Field                                      |
|---|-----------------|--|
| 303(d)  | Yes             | METALS- MERCURY  |
| Wetland<br>Species  | No              | N/A  |
| Rare and<br>Imperiled   | No              | N/A  |
| Land Use/<br>Cover  | No              | N/A  |
| Candidate<br>Mussels  | No              | N/A  |
| Sturgeon<br>C.H.  | Yes             | N/A  |
| Additional Site Features Stream Channel Woody Material: Impoundments: Substrate Composition: Bank Material: |                 | r <u>ial</u> : Moderate<br>None<br>Medium Sand<br>Sand |

Notes: None