Shoal River

ok-0423-003

Severity Score

Common:3.5mi E of Crestview, Piney Woods Creek confluenceDrainage:Shoal RiverGPS: 30.747224508, -86.515099394

<u>Land owner</u>: RB: Purl G Adams Jr. / LB: George & Essie Mack

<u>County</u>: <u>PLSS(T-R-S)</u>: <u>Parcel No.</u>:

Okaloosa 3N-23W-23 1/ 1.0140 State: Florida





Risk Factor	Ranking	Score
Channel Stability	Fair	1
Channel Alteration	In Recovery	1
Bank Erosion	Active	1
ВЕНІ	High	1
Local NPSP	Moderate Potential	1
Shoring Structures	Not Present	0
Pipe Discharge	Not Present	0
Water Odors	Not Present	0
Fish Passage Barrier	Not Present	0
RB: Riparian Buffer	0-29 ft	0.75
LB: Riparian Buffer	0-29 ft	0.75
RB: Floodplain Access	Partial	0.25
LB: Floodplain Access	Partial	0.25
	River Threat Index:	7

Feature	Within Range	Descriptive Field
303d	No	N/A
Wetland Species	Yes	1-3 FOCAL SPECIES IN UPLAND AREAS
Rare and Imperiled	Yes	GOLDSTRIPE DARTER, SPECKLED CHUB IRONCOLOR SHINER
Land Use/ Cover	Yes	NA/ PINE FLATWOODS
Candidate Mussels	No	N/A
Sturgeon C.H.	No	N/A
Additional Site Features Stream Channel Woody Material: Moderate		

Impoundments: None

<u>Substrate Composition</u>: Medium Sand and Coarse Sand

Bank Material: Sand

Notes: Residence on left bank across from site. Site adjacent to power line crossing and below Hwy 90. Dead mussels found at this site. Live corbiculla also found.