## Unnamed tributary

## wa-0706-r-001

Sedimentation Risk Index

Florida

**28** 

State:

8.6mi SW of Florala Common:

Drainage:
Land owner: Pine Log Creek <u>GPS:</u> 30.886233, -86.372805 Carolyn Dixon- US, Unknown-DS <u>County</u>: <u>PLSS(T-R-S)</u>: <u>Parcel No.</u>: Walton 5N-21-31

Road Name: Allen Rd





Crossing Structure: DS

Risk Factor	Ranking	Score
US Channel Morph	PONDED	1
DS Channel Morph	PONDED	1
DS Bank Alteration	HIGH	1
Upstream Skew Angle	>30°	1
Crossing fill condition	Fair/Rip Rap	3
Inlet/Outlet Condition	Blocked	1
Road Approach Material	All Aggregate	5
Potential Eroded Volume Mean	<21 y <sup>3</sup>	5
Approach Slope Mean	2.1-4%	3
Soil K Factor	< 0.20	5
Upstream Rt Outlet	Concrete	0
Upstream Lt Outlet	Concrete	0
Upstream Rt Ditch	Concrete	0
Upstream Lt Ditch	Concrete	0
Downstream Rt Outlet	Concrete	0
Downstream Lt Outlet	Concrete	0
Downstream Rt Ditch	Concrete	0
Downstream Lt Ditch	Concrete	0
Outlet Total	Unimproved Outlet System	1
Ditches Total	Unimproved Drainage System	1
SRI Total	High Risk	28

			Consegue
	400	<b>新</b>	世紀
	1	Okaloosa	Walten
機構	ate.		
	<b>等</b>		
			Google

Outtet Total	Ommproved Oddet System	1
Ditches Total	Unimproved Drainage System	1
SRI Total	High Risk	28
Additional Site Features		
Crossing Type and Quantity	: Culvert, 2	
Crossing Materials:	Metal	
Soil Types:	2,10,11,14,13,15,25,26,29	9,35
Rt Approach Prism Fill:	0.25in	
It Approach Prism Fill	0.25in	

Feature	Within Range	Descriptive Field
303(d)	No	N/A
Wetland Species	No	N/A
Rare and Imperiled	No	N/A
Land Use/ Cover	Yes	AGRICULTURAL,PARCELS WITH NO VALUES/ WETLAND FORESTED MIX
Candidate Mussels	No	N/A
Sturgeon C.H.	No	N/A

Notes: DS drop off