Atwell Pond

sr-0414-r-005

Sedimentation Risk Index

40

Florida

State:

Common: 6.7mi S of Harold

Poplar Branch
US Government- Eglin AFB <u>Drainage</u>: Land owner:

County: GPS: 30.561150, -86.873011 $\overline{PLSS(T-R-S)}$:

Parcel No.:

Santa Rosa 1N-26-29

Road Name: RR 211-Eglin AFB





Crossing Structure: DS

core	
1	

Risk Factor	Ranking	Score
US Channel Morph	PONDED	1
DS Channel Morph	Е	5
DS Bank Alteration	MINOR/PARTIAL	3
Upstream Skew Angle	<5°	5
Crossing fill condition	Good/Vegetated	5
Inlet/Outlet Condition	No Impairment	5
Road Approach Material	All Sand/Clay	3
Potential Eroded Volume Mean	>40 y ³	1
Approach Slope Mean	<2%	5
Soil K Factor	< 0.20	5
Upstream Rt Outlet	Bare soil	0
Upstream Lt Outlet	Bare soil	0
Upstream Rt Ditch	Bare soil	0
Upstream Lt Ditch	Bare soil	0
Downstream Rt Outlet	Bare soil	0
Downstream Lt Outlet	Bare soil	0
Downstream Rt Ditch	Bare soil	0
Downstream Lt Ditch	Bare soil	0
Outlet Total	Unimproved Outlet System	1
Ditches Total	Unimproved Drainage System	1
SRI Total	Medium Risk	40

		製
	Santa Resa	
	The same of the sa	THE THE
	A 2 10 F 3	À
	7	4 ** 4
	是 等人,唯	
		Google

Additional Site Features Crossing Type and Quantity: Culvert,1; Stand Pipe, 1 **Crossing Materials**: Reinforced Concrete; Metal 7,21,23,46 Soil Types: Rt Approach Prism Fill: 1.0in Lt Approach Prism Fill: 0.5in

Feature	Within Range	Descriptive Field
303(d)	No	N/A
Wetland Species	Yes	1-3 FOCAL SPECIES IN UPLAND AREAS
Rare and Imperiled	No	N/A
Land Use/ Cover	Yes	PUBLIC/SEMI-PUBLIC/ N/A
Candidate Mussels	No	N/A
Sturgeon C.H.	No	N/A

Notes: Recreational site-possible fishing pond.