Long Creek

wa-1007-003

Severity Score

Common: 13mi S of Florala

<u>Drainage</u>: Pond Creek <u>GPS</u>: 30.816668947, -86.383371139

Land owner: LB: John & Leah Smith / RB: David & Toni Mayo

<u>County</u>: <u>PLSS(T-R-S)</u>: <u>Parcel No.</u>: Walton 4N-21W-30 1.041 / 1 State: Florida





Risk Factor	Ranking	Score
Channel Stability	Good	0.5
Channel Alteration	In Recovery	1
Bank Erosion	Active	1
BEHI	Historic	0.5
Local NPSP	Moderate Potential	1
Shoring Structures	Present	1.5
Pipe Discharge	Not Present	0
Water Odors	Not Present	0
Fish Passage Barrier	Not Present	0
RB: Riparian Buffer	0-29 ft	0.75
LB: Riparian Buffer	0-29 ft	0.75
RB: Floodplain Access	Full	0
LB: Floodplain Access	Full	0
	River Threat Index:	7

Feature	Within Range	Descriptive Field
303(d)	No	N/A
Wetland Species	Yes	1-3 FOCAL SPECIES IN WETLAND AREAS
Rare and Imperiled	No	N/A
Land Use/ Cover	Yes	VACANT RESIDENTIAL/ WETLAND FORESTED MIX
Candidate Mussels	No	N/A
Sturgeon C.H.	No	N/A
Additional S Stream Chai Impoundmen	nnel Woody	

Medium Sand

Sand and Clay

Notes: Site located on private rd-Hickory Tree Ln. Note nearby impoundment in aerial.

Private bridge and power line crossing. Sediment load coming from power line crossing

and large culverts under road before bridge crossing.

Substrate Composition:

Bank Material: