Dry Creek

co-0820-r-004

Sedimentation Risk Index

40

Alabama

State:

5.3mi N of Florala Common:

Drainage: Clear Creek <u>GPS:</u> 31.080673255, -86.341286533

Land owner: Rayonier Forest Resources LP <u>County</u>: <u>PLSS (T-R-S)</u>: Covington 1N-17E-3

<u>Parcel No.</u>: Road Name: Tram Rd





Crossing Structure: US

DS	

Risk Factor	Ranking	Score
US Channel Morph	WETLAND	5
DS Channel Morph	Е	5
DS Bank Alteration	HIGH	1
Upstream Skew Angle	<5°	5
Crossing fill condition	Poor/Bare soil	1
Inlet/Outlet Condition	Sed Islands/Scouring	3
Road Approach Material	All Sand/Clay	3
Potential Eroded Volume Mean	21-40 y ³	3
Approach Slope Mean	<2%	5
Soil K Factor	< 0.20	5
Upstream Rt Outlet	Vegetated	1
Upstream Lt Outlet	Vegetated	1
Upstream Rt Ditch	Bare soil	0
Upstream Lt Ditch	Bare soil	0
Downstream Rt Outlet	Vegetated	1
Downstream Lt Outlet	Bare soil	0
Downstream Rt Ditch	Bare soil	0
Downstream Lt Ditch	Bare soil	0
Outlet Total	Partially Improved Outlet System	3
Ditches Total	Unimproved Drainage System	1
SRI Total	Medium Risk	40
Additional Site Feature	es	
Crossing Type and Qua		
Crossing Materials:	Metal	
Cail Taman	Mh A Ec A	

0.75in

MbA, FoA 2.0in



Feature	Within Range	Descriptive Field	
303(d)	No	N/A	
Wetland Species	No	N/A	
Rare and Imperiled	No	N/A	
Land Use/ Cover	No	N/A	
Candidate Mussels	No	N/A	
Sturgeon C.H.	No	N/A	

Notes: None.

Soil Types: Rt Approach Prism Fill:

Lt Approach Prism Fill: