## Horsehead Creek

## co-0731-r-012

Sedimentation Risk Index

46

Alabama

State:

4.7mi SW of Florala Common:

Drainage:
Land owner: Pond Creek <u>GPS:</u> 30.995696, -86.406183 Rayonier Forest Resources LP

<u>County</u>: <u>PLSS (T-R-S)</u>: Covington 6N-22W-26

<u>Parcel No.</u>:

Road Name: Davis Rd





**Crossing Structure: DS** 

Risk Factor	Ranking	Score
US Channel Morph	DA	3
DS Channel Morph	С	5
DS Bank Alteration	MINOR/PARTIAL	3
Upstream Skew Angle	<5°	5
Crossing fill condition	Fair/Rip Rap	3
Inlet/Outlet Condition	No Impairment	5
Road Approach Material	All Sand/Clay	3
Potential Eroded Volume Mean	<21 y <sup>3</sup>	5
Approach Slope Mean	>4%	1
Soil K Factor	< 0.20	5
Upstream Rt Outlet	Vegetated	1
Upstream Lt Outlet	Vegetated	1
Upstream Rt Ditch	Synthetic	1
Upstream Lt Ditch	Bare soil	0
Downstream Rt Outlet	Vegetated	1
Downstream Lt Outlet	Vegetated	1
Downstream Rt Ditch	Bare soil	0
Downstream Lt Ditch	Bare soil	0
Outlet Total	Improved Outlet System	5
Ditches Total	Partially Improved Drainage System	3
L ove Diale		

		Corington
		(Kalong) Walter
Transplant For 2 Total	Charle of Carl	Google

		-
SRI Total	Low Risk	46
Additional Site Features		
Crossing Type and Quantity:	Bridge, 1	
Crossing Materials:	Wood	
Soil Types:	BoC,DmB,EuA,FuB,MBA,Tr	D
Rt Approach Prism Fill:	0.25in	
It Approach Prism Fill:	0.1in	

Feature	Within Range	Descriptive Field
303(d)	No	N/A
Wetland Species	No	N/A
Rare and Imperiled	No	N/A
Land Use/ Cover	No	N/A
Candidate Mussels	No	N/A
Sturgeon C.H.	No	N/A

Notes: None

46