Little Creek

wa-0626-r-002

Sedimentation Risk Index

44

Florida

State:

6.8mi SE of Florala Common:

Drainage:
Land owner: Long Creek <u>GPS:</u> 30.911752, -86.287466 Ronald & Joan Earley-US, Mary Prater McLean-DS <u>County</u>: <u>PLSS(T-R-S)</u>: <u>Parcel No.</u>: Walton

5N-20-19/30 6.001, 5 Road Name: Campground Rd





Crossing Structure: DS

Risk Factor	Ranking	Score
US Channel Morph	С	5
DS Channel Morph	С	5
DS Bank Alteration	MINOR/PARTIAL	3
Upstream Skew Angle	<5°	5
Crossing fill condition	Poor/Bare soil	1
Inlet/Outlet Condition	No Impairment	5
Road Approach Material	All Sand/Clay	3
Potential Eroded Volume Mean	21-40 y ³	3
Approach Slope Mean	<2%	5
Soil K Factor	0.21-0.40	3
Upstream Rt Outlet	Vegetated	1
Upstream Lt Outlet	Vegetated	1
Upstream Rt Ditch	Bare soil	0
Upstream Lt Ditch	Bare soil	0
Downstream Rt Outlet	Vegetated	1
Downstream Lt Outlet	Vegetated	1
Downstream Rt Ditch	Bare soil	0
Downstream Lt Ditch	Bare soil	0
Outlet Total	Improved Outlet System	5
Ditches Total	Unimproved Drainage System	1

			Consigna
	362	Chalcon	Water
John State State State			oogle

Downstream Rt Ditch	Bare soil	
Downstream Lt Ditch	Bare soil	
Outlet Total	Improved Outlet System	
Ditches Total	Unimproved Drainage System	
SRI Total	Medium Risk	44
Additional Site Features		
Crossing Type and Quantit	<u>ty</u> : Culvert, 2	
Crossing Materials:	Metal	
Soil Types:	6,29,40,60	
Rt Approach Prism Fill:	0.5in	
Lt Approach Prism Fill:	0.5in	

Feature	Within Range	Descriptive Field
303(d)	Yes	COLIFORMS
Wetland Species	No	N/A
Rare and Imperiled	No	N/A
Land Use/ Cover	Yes	AGRICULTURAL/ HAY FIELDS
Candidate Mussels	No	N/A
Sturgeon C.H.	No	N/A

Notes: Dry at time of survey. 2 culverts of different diameter